

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
 GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : TOH SOH LING SANDY  
 271 CHOA CHU KANG AVE 2  
 #13-261  
 SINGAPORE 680271

Estimate No: MC1901719  
 Date: 02 Feb 2021  
 Policy No: MT/00874046  
 Veh Reg No: SKZ8104P  
 Make/Model: HONDA JAZZ 1.5 VTIR CVT

ATTN:

*UIC 1030*

Your Ref No: SKZ8104P  
 Claim Type: Third Party → *MC*  
 Accident Date: 31/01/2021  
 TP Veh Reg No: SMR4200P

*Not As noted  
 UIC 8  
 Recovery After Pain  
 3 day*

**Estimate Repair Cost to Vehicle No :SKZ8104P**

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
<b>SPARE PARTS</b>			
1 REAR WINDSCREEN MOULDING	1 PC	<i>mc</i> 95.60	<input checked="" type="checkbox"/>
2 TAILGATE	1 PC	<i>mc</i> 730.60	<input checked="" type="checkbox"/>
3 TAILGATE CHROME MOULDING	1 PC	<i>mc</i> 234.40	<input checked="" type="checkbox"/>
4 TAILGATE EMBLEM	1 PC	<i>mc</i> 15.70	<input checked="" type="checkbox"/>
5 TAILGATE JAZZ LOGO	1 PC	<i>mc</i> 10.90	<input checked="" type="checkbox"/>
6 REAR BUMPER	1 PC	492.60	<input checked="" type="checkbox"/>
7 REAR BUMPER SIDE RETAINER LH & RH	2 PC	<i>mc</i> 25.00	<input checked="" type="checkbox"/>
8 REAR BUMPER CLIPS	12 PC	42.00	<input checked="" type="checkbox"/>
		1,646.80	
	Less 20%	329.36	1,317.44
<b>Special Nett</b>			
9 REVERSE SENSOR	1 SET	<i>mc</i> 200.00	<input checked="" type="checkbox"/>
		200.00	200.00
<b>LABOUR</b>			
10 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	<input checked="" type="checkbox"/>
11 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	<input checked="" type="checkbox"/>
12 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<input checked="" type="checkbox"/>
13 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	<i>30d</i>
14 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR END PANEL,SPARE TYRE PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>30d</i>
15 TO SPRAY TAILGATE,REAR BUMPER.	1 PC	500.00	<i>40d</i>
		1,300.00	1,300.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Completed by Repairer

