

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TOH SOH LING SANDY
 271 CHOACHU KANG AVE 2
 #13-261
 SINGAPORE 680271

Estimate No: MC1901719
 Date: 02 Feb 2021
 Policy No: MT/00874046
 Veh Reg No: SKZ8104P
 Make/Model: HONDA JAZZ 1.5 VTIR
 CVT

ATTN:

LC12 1030

Your Ref No: SKZ8104P
 Claim Type: Third Party → *ME*
 Accident Date: 31/01/2021
 TP Veh Reg No: SMR4200P

*Not As quoted
 LC12P @ 1250h
 Resurvey After Paint
 3 days*

Estimate Repair Cost to Vehicle No :SKZ8104P

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR WINDSCREEN MOULDING	1 PC	<i>me</i> 95.60	<input checked="" type="checkbox"/>
2 TAILGATE	1 PC	<i>By</i> 730.60	<input checked="" type="checkbox"/>
3 TAILGATE CHROME MOULDING	1 PC	<i>su</i> 234.40	<input checked="" type="checkbox"/>
4 TAILGATE EMBLEM	1 PC	<i>nn</i> 15.70	<input checked="" type="checkbox"/>
5 TAILGATE JAZZ LOGO	1 PC	<i>me</i> 10.90	<input checked="" type="checkbox"/>
6 REAR BUMPER	1 PC	<i>R</i> 492.60	<input checked="" type="checkbox"/>
7 REAR BUMPER SIDE RETAINER LH & RH	2 PC	<i>su</i> 25.00	<input checked="" type="checkbox"/>
8 REAR BUMPER CLIPS	12 PC	<i>nn</i> 42.00	<input checked="" type="checkbox"/>
		1,646.80	
	Less 20%	329.36	1,317.44
Special Nett			
9 REVERSE SENSOR	1 SET	<i>su</i> 200.00	<input checked="" type="checkbox"/>
		200.00	200.00
LABOUR			
10 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	<input checked="" type="checkbox"/>
11 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	<input checked="" type="checkbox"/>
12 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	<i>nn</i> 60.00	<input checked="" type="checkbox"/>
13 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	<i>3d</i>
14 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR END PANEL,SPARE TYRE PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>30d</i>
15 TO SPRAY TAILGATE,REAR BUMPER.	1 PC	500.00	<i>40d</i>
		1,300.00	1,300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TOH SOH LING SANDY
271 CHOA CHU KANG AVE 2
#13-261
SINGAPORE 680271

Estimate No: MC1901719
Date: 02 Feb 2021
Policy No: MT/00874046
Veh Reg No: SKZ8104P
Make/Model: HONDA JAZZ 1.5 VTIR
CVT

ATTN:

Your Ref No: SKZ8104P
Claim Type: Third Party
Accident Date: 31/01/2021
TP Veh Reg No: SMR4200P

Estimate Repair Cost to Vehicle No :SKZ8104P

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 2,817.44
		Add GST @ 7%	197.22
		Total Amount Payable	S\$ 3,014.66

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOURTEEN AND CENTS SIXTY SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE