

Enquire Vehicle Owner Details (As At 30 Jan 2021 / 10:40:00)

Vehicle Owner Details

Owner ID Type:

Company

Owner Name:

GRAB RENTALS PTE. LTD.

Registered Block/House No.:

6

Registered Unit No.:

38 - 04

Registered Postal Code:

049909

Owner ID:

201617200G

Registered Address Type:

Private Residential (Condo Apt or House) /

Shopping / Office Complexes

Registered Street Name:

BATTERY ROAD

Registered Building Name:

Vehicle Insurance Details

Vehicle No.:

SLH7291X

Make Description/Model:

HONDA / VEZEL HYBRID 1.5X AUTO

Insurance Company Name:

MSIG INSURANCE (SINGAPORE) PTE LTD

Insurance Company Name:

INDIA INT'L INS PTE LTD

Printed on 02 Feb 2021 09:49:59

Copyright © Land Transport Authority of Singapore 2021



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- In Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/01/2021 14:55 (SGT)
Date of Accident	30/01/2021 10:40 (SGT)
Exact Location of Accident	Near 33 Jln Afifi, Singapore 409180
itional Location Information	PIE EXITING TO PAYA LEBAR ROAD
Country/State of Loss	Singapore

13/04/1955

Indoor

DETAILS O	F OWN VEHICLE
Vehicle-Registration-Number	SLF4507E
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner NRIC No Email Address Mobile Phone No Alternative Phone No	No KOH YEW BENG SXXXX229F IVAN2169@GMAIL.COM (Phone) +65-97366541 (Home) +65-97366541
VEHICLE PARTICULARS	
Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category INSURANCE COMPANY	Honda Vezel Private use No - Claiming third party Private car
Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number	Direct Asia Comprehensive No MT/00843995
Name of Driver	KOH YEW BENG

Date Of Birth

Occupation

Date Of Driving Pass Driving experience	21/11/1987 33 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97366541
Alt. Phone Number	(Home) +65-97366541
Email Address	· · · · ·
Address	IVAN2169@GMAIL.COM
Address complement	BLK 314 TAMPINES STREET 33 #11-32
Postcode	E00044
Is the driver the policyholder?	520314
	Yes
If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles?	
	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	-
insurance company of other vehicle owned by briver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry
THER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s)	•
soliciting/offering accident claims assistance?	No
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-
OIDOUNGTANGES OF ACCIDENT	
CIRCUMSTANCES OF ACCIDENT	
ER TO SKETCH PLAN	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No
*	
DETAIL O OF OTHER	VEHICLE PROPERTY 4
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number	SLH7291X
Vehicle Manufacturer	<u>¥</u>
rate and the standard	

Vehicle Registration Number	SLH7291X
Vehicle Manufacturer	-
Vehicle Model) <u>=</u> 1
Vehicle Variant	-
Vehicle Colour	/ = /
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	: <u>*</u>
Address complement	-
Postcode	: <u>=</u> 2
Insurance Company Name	

Nature Of Damage	,
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	KOH YEW BENG
Address	<u>#</u>
Address Complement	i iii
Post Code	
Approximate Age Years Old	1 E
Injuries Sustained	.(≦i
Injured person in which vehicle?	SLF4507E
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No
, , , , , , , , , , , , , , , , , , , ,	110

	inhal time and date
my vehicle	e A braving sleasoff was garrovory while
Waiting to	ext, imp paya Larav road, when suddinly
1 RH an II	mipset from my rear and realised ventre B
beauting SLI	H FORIX had collected on to my year.

Declaration

Who declare the foregoing particulars are true in every respect.

Folicy Letter's September / Date &

Driver's Signature (# driver is not the policyholder) / Duto & Time

Witnessed by Reporting Centre Personnel

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the clams process.
- 2 This Formmust be completed by the Policyholder and/or the Authorised Oriver
- 3. Information provided must be as <u>In Whitel and accurate as possible</u>. Any wiful materioresentation or wishbutting of imiterial facts may above insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any laise reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesed.
- 8. Consent under the Personal Data Protection Act (PDPA)

funderstand, acknowledge, agree and consent that

(a) My insurer in my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by the or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers; who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yersitaw from the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim.

(ii) investigating the acordent and/or my claims.

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by mo-

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or netices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes mad packages), and/or

(v) complying with applicable law in administering processing handling and or dealing with ny claims

(collectively the 'Purposes')

(b) all insurers) who have insured vehicles) involved in this accident and the Insurers lawyers law firms, may/are permitted to collectuse, disclose and/or process my Personal information for one or more of the above Parposes, and

(c) my Personal information may/can be disclosed by any of trie insurers' and or GA to their trind party service providers or algents (including their lawyers law firms), which may be sted outside of Singapore, for one or mare of the above Purposes.

Pole Jer's Sign Jure / Onte &

Skotch Plan

PIE EXT TO

PHYAILEBRE RD

Driver's Signature (# driver is not the policyholder) / Date & Time

Witnessay of Reporting Centre Personnel

A-SLF4507E

B-SLHIZORIX

direct asia

Contact us at

Hotline: (65) 6532 2888

E-mail: CustomerService@DirectAsia.com

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act") Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore) Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be arrested or updated.

Certificate No.

MT/00843995

Type of Coverage / Driver Plan

Car Comprehensiva (Value Plus Plan)

1) Vehicle Registration No.

SLF4507E

Chassis No.

RU11205518

2) Name of Policy Holder

KOH YEW BENG

3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act

26/08/2020 00:00

4) Date/Time of Expiry of Insurance

25/08/2021 23:59

- 5) Persons or Classes of Persons Entitled to Drive
 - (a) Any named person under the policy who is driving on the Policyholder's permission.
 - (b) Any authorised person, provided such person is aged 30 and above and holds a valid driving licence of 2 years or more, who is driving on the Policyholder's permission

The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.

6) Limitations as to use"

Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business. Private car-pooling arrangements where you commute with passengers and split the fuel expense is covered under the standard policy. Grab Hitch will only be covered if this is the declared usage stated on your Policy Schedule. Only two rides are permitted a day. Other forms of commercial car-pooling or any ride hailing services (e.g. Grab, Go-Jek etc.) are not allowed.

'Umitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.

Sum Insured

Market Value

Own Damage Excess

S\$ 800,00 (before any applicable GST)

Windscreen Excess

S\$ 100.00 (before any applicable GST)

Choice of workshop

DirectAsia approved workshops

Finance company / Hire Purchase

Main driver

KOH YEW BENG

Named deliver

None

Important Note: This policy does not cover the policyholder/drivers below the age of 30 and Policyholder/drivers who hold a valid driving licence of less than 2 years with the exception of the main/named drivers above.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Issued on:

24/08/2020

Direct Asia Insurance (Singapore) Pte. Ltd.

Underwriting Manager

Direct Asia Insurance (Singapore) Pto Ltd 20 Anson Road #08-01 Twenty Arison Singapore 079912 www.DirectAsia.com



1 KAKI BUKIT AVENUE 6 #01-111 AUTOBAY@KAKI BUKIT SINGAPORE 417883 TEL: 6747 1811 6749 4390 FAX: 6745 1596 Business Reg. No: 24171400A

20-Feb-21

Koh Yew Beng Blk 314 Tampines St 13 #11-32 Singapore 520314

Dear Officer In Charge,

Final Repair Bill to vehicle number SLF4507E Accident date: 30 January 2021

Lump Sum repair

\$ 7,400.00

\$ 7,400.00

Total: Seven Thousand and Four Hundred Dollar only.

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189 Mobile: 9061 0543 Email: mirage1195@gmail.com

ACCIDENT VEHICLE INSPECTION REPORT

Report no

: 49M0221.MW

Vehicle no

: SLF4507E

1 REFERENCE

Date of inspection

: 3 February 2021

Requested by

: Koh Yew beng

Blk 314 Tampines Street 33

#11-32

Singapore 520314

Type of survey

: Independent

Repairer

: Manwell Auto

Blk 1 Kaki Bukit Ave 6, #01-111 AutoBay @ Kaki Bukit, Singapore 417883

Date of accident

: 30 January 2021

2 VEHICLE DATA

Make/model

: HONDA VEZEL 1.5X A

Chassis no

: RU11205518

Engine no

: L15B4405518

Date of registration

: 26 August 2016

COE Expiry Date:

25 August 2026

Engine capacity

: 1496 cc

Odometer reading

: 095069 km

Colour

Red

3 STATIC CONDITION CHECK

Steering

: Serviceable

Foot brakes

: Serviceable

Hand brakes

: Serviceable

Paintwork

: Good

General Condition

: Good

TIRE CONDITION CHECK RH/MAKE

LH/MAKE

SIZE

Front tread

: 6 mm/Goodyear

6 mm/Goodyear

215/60R16

Rear tread

: 6 mm/Goodyear

6 mm/Goodyear

215/60R16

BRIEF DESCRIPTION OF DAMAGE

Tail gate dented/bent/distorted, taillamp base panels bent, rear end panel dented/bent/distorted, spare tyre panel bent, rear bumper dented/squashed/deformed, etc. Please see para. 8 of this report for more details.

6 **REMARKS**

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs

\$7,400.00 (lump sum)

Estimated no of days

Six (6)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no:

49M0221.MW

Vehicle no:

SLF4507E

Α	SPARE PARTS		Assessed			Damainaula	Davidson
	Description	Qty				Repairer's	<u>Revised</u>
	Tail gate assy		badly dented/bent/distorted	J		Amount	Amount
	Tail gate lock assy	1	bent/distorted	ı		1,450.70	1,450.70
	Tail gate lock lower striker	1	bent			167.40	167.40
	Tail gate "VEZEL" emblem	1	necessary			22.40	22.40
	Tail gate centre centre garnish	1	clip bracket broken			56.40	56.40
	Tail gate centre centre garnish logo	1	necessary			325.00	325.00
	Tail gate centre centre garnish clip	4	necessary			28.70	28.70
	Tail gate side reflector lamp assy LH	1	casing cracked			23.20	23.20
	Tail gate side reflector lamp assy RH	1	casing cracled			378.60	378.60
	Tail gate gas shock stay LH/RH	2	bent/stiffened			378.60	378.60
	Tail gate weatherstrip	1	grip channel deformed			221.00	221.00
	Tail gate trim board c/retaining clip	1	inner ribs bent/deformed			198.20	198.20
	Tail gate hand open bezel	1	bent/ribs broken			225.50	225.50
	Tail gate open switch assy	1	bracket broken			25.80	25.80
	Rear windscreen moulding	_				108.50	108.50
	Rear wiper motor	1	necessary			148.20	148.20
	LH taillamp assy	1	shaft bent/wobbled			283.70	283.70
	LH taillamp side clip	1	leg bent/cracked			482.40	482.40
	LH tail lamp base panel	1	necessary			6.50	6.50
	RH taillamp assy	1	to repair			178.90	0.00
	RH taillamp side clip	1	leg bent/cracked			482.40	482.40
	RH tail lamp base panel	1	necessary			6.50	6.50
	Rear bumper	1	to repair			178.90	0.00
	Rear bumper side cover LH/RH	1	dented/squashed/deformed			532.10	532.10
	Rear bumper side retainer LH/RH	2	lock tabs bent/deformed			333.60	333.60
	Rear bumper reflector LH/RH	2	grip tabs broken			114.60	114.60
	Rear end panel	2	casing broken			282.40	282.40
	Rear end panel trim c/w clip	1	dented/bent/distorted			482.70	482.70
	Rear end panel buzzer	1	ribs bent/deformed			145.70	145.70
	Spare tyre panel		mounting leg broken			162.80	162.80
1	Spare tyre panel top board		to repair			693.50	0.00
	Spare tyre panel styrofoam tool tray		serviceable			194.70	0.00
	Rear license plate lamp LH/RH		serviceable			232.70	0.00
	Rear licelise place lamp LH/KH	2	leg bent/fractured		-	80.60	80.60
			Subtotal of the above			8,632.90	7,154.20
	(Special nett)		Discount	20%/	20%_	1,726.58	1,430.84
	Rear windscreen gum		Subtotal 1:			6,906.32	5,723.36
	Reverse sensor set		necessary			80.00	80.00
	Parking camera set		broken/shorted			280.00	280.00
	Rear number plate c/frame set		shorted			580.00	580.00
	Real Humber plate C/Hame Set		scraped		1	70.00	70.00
			Subtotal 2:			1,010.00	1,010.00
D	LADOUR		Total cost of parts:		-	7,916.32	6,733.36
<u>B</u>	LABOUR To check wiring and lighting and rectify factors	ults v	where needed.			45.00	30.00
						75.00	30.00
	To install reverse sensors and check sensing	ng fu	nctions.			80.00	60.00
	To apply anti-rust undercoat.					120.00	90.00

To remove and reinstall rear windscreen glass.	140.00	120.00
To remove and transfer tail gate fittings and attachments to new tail gate.	120.00	60.00
Labour charges to remove and replace, to cut and weld, to panel beating affected and damaged parts.	1,000.00	750.00
Spray painting charges to paint the rear end panel, spare tyre panel, tail gate, tail light base panels, rear bumper side covers and necessary areas.	1,500.00	1,250.00
To install parkign camera and check funtions.	120.00	90.00
Total cost of labour:	3,125.00	2,450.00
Total cost of repair:	11,041.32	9,183.36
CONCLUSION		

9

The revised or adjusted cost of repairs to restore the vehicle is

\$9,183.36

(a) However, the recommended cost of repair based on lump sum basis would be

\$7,400.00

(b) The number of days taken to complete the repairs are

Six (6)

(1st re-inspection conducted on 3 February 2021) (Post Repair Inspection conducted on 8 February 2021)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its preaccident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Yours faithfully

Liaw Leong San

Licensed Automotive Appraiser

Dated:

10 February 2021

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189 Mobile: 9061 0543 Email: mirage1195@gmail.com

Koh Yew beng Blk 314 Tampines Street 33 #11-32 Singapore 520314

\$30

Invoice no:	POS049/21
Date:	10 February 2021
Report no:	49M0221.MW
Vehicle :	SLF4507E

INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle transport and photographs.			808.00
SGD(\$):	Eight Hundred and Eight only	Payal	ble Amount:	808.00

[&]quot;Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES

Authorised Signature















Report no: 49M0221.MW


Vehicle no: SLF4507E
















Report no: 49M0221.MW


























































































































Report no:

49M0221.MW











