

**Veron Chen (LKKAUTO)**

---

**From:** Lim, Kok-Chong <Kok-Chong.Lim@aig.com>  
**Sent:** Wednesday, 3 February 2021 12:24 PM  
**To:** Veron Chen (LKKAUTO)  
**Cc:** SUR  
**Subject:** Re: SMM 7878R-DOA: 30/1/21 (AIG REF: 5240863524SG)

Hi Veron,

Pls ignore my remarks and proceed with surveyor recommendation.

Has contacted Steve to clarify

Best Regards,

**LIM KOK CHONG**  
**AIG**  
**Senior Motor Surveyor**  
**Claims | AIG Asia Pacific Insurance Pte. Ltd.**

**78 Shenton Way, Level 10**  
**Singapore 079120**  
**Mobile +(65) 8876 5437**  
[kok-chong.lim@aig.com](mailto:kok-chong.lim@aig.com) | [www.AIG.sg](http://www.AIG.sg)

On 3 Feb 2021, at 12:18 PM, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

**This message is from an external sender; be cautious with links and attachments.**

Dear Kok Chong,

**Refer to Labour #3 should be 7 panels (\$2450)**

Repairer would like to know what are the 7 panels.

Kindly assist to list out.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must

not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.