

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 30.01.21
 Emailed : 10.02.2021, 5.55pm
 Date Survey : 02.02.2021

VEHICLE NO : SMM 7878 R
 MODEL : MIT OUTLANDER 2.0
 WIP : 62529

Material	:	\$	<u>9,718.94</u>
Labour	:	\$	<u>5,040.00</u>
Sub-Total	:	\$	<u>14,758.94</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>14,158.94</u>
GST 7%	:	\$	<u>991.13</u>
Grand Total	:	\$	<u>15,150.07</u>
Finalise By/Date	:	<u>LOI / 10/02/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 02/02/2021	Cust No/Name	KCV11369/CHAN HWEE MIN FELICIA
	Reg No/Reg Date	SMM7878R / 24/05/2019
	Date In/Mileage	02/02/2021/ 26975
	Chassis/Package	GF7W0600727 /DC17P(F)
	Engine No	4J11AC6616
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	10/02/2021/ 16:47	BLC	260 / AiTing	62529			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, FRONT SUPPORT PANEL, LH FRONT FENDER, REPAIR RH FRONT FENDER, LH & RH FRONT DOOR, LH FRONT A PILLAR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1800.00
E PNT88000 REMOVE & INSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR								✓ 100.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, LH & RH FRONT FENDER, LH & RH FRONT DOOR, LH FRONT A PILLAR, FRONT SUPPORT PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 2800.00
A 54900099 VACUUM & TOP UP A/COND GAS								✓ 80.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORTIONS								✓ 40.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								✓ 50.00
X EXC EXCESS FOR OWN DAMAGE CLAIM								-600.00
X FACE,FR BUMPER					1.00	✓ 859.00	23.00	661.43
X BRACKET,FR BUMPER SIDE,LH					1.00	✓ 18.00	23.00	13.86
X EXTENSION,FR BUMPER					1.00	✓ 515.00	23.00	396.55
X BRKT,FR BUMPER SIDE,LWR RH					1.00	✓ 5.00	23.00	3.85
X BRKT,FR BUMPER SIDE,LWR LH					1.00	✓ 6.00	23.00	4.62
X GARNISH,FR BUMPER SIDE					1.00	✓ 112.00	23.00	86.24
X COVER,FR BUMPER					1.00	✓ 359.00	23.00	276.43
X GARNISH,FR LICENSE PLATE					1.00	✓ 23.00	23.00	17.71

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11369/CHAN HWEE MIN FELICIA Reg No/Reg Date SMM7878R / 24/05/2019 Date In/Mileage 02/02/2021/ 26975 Chassis/Package GF7W0600727 /DC17P(F) Engine No 4J11AC6616 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim X04 BLACK / BK BLACK
02/02/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/02/2021/ 16:47	BLC	260 / AiTing	62529
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X REINFORCEMENT,FR BUMPER		1.00	✓ 134.00	23.00	103.18
X REINF,FR BUMPER SIDE,RH		1.00	✓ 69.00	23.00	53.13
X REINF,FR BUMPER SIDE,LH		1.00	✓ 60.00	23.00	46.20
X COVER,HEADLAMP SUPT PANEL		1.00	✓ 50.00	23.00	38.50
X GRILLE ASSY,RADIATOR		1.00	✓ 548.00	23.00	421.96
X HOOD		1.00	✓ 975.00	23.00	750.75
X INSULATOR,HOOD		1.00	✓ 133.00	23.00	102.41
X LATCH,HOOD		1.00	✓ 76.00	23.00	58.52
X FENDER,FR LH		1.00	✓ 688.00	23.00	529.76
X MOULDING,FR BUMPER,LH		1.00	✓ 116.00	23.00	89.32
X MOULDING,FR BUMPER,RH		1.00	✓ 116.00	23.00	89.32
X MOULDING,FR WHEEL ARCH,RH		1.00	✓ 160.00	23.00	123.20
X MOULDING,FR WHEEL ARCH,LH		1.00	✓ 160.00	23.00	123.20
X PANEL,HEADLAMP SUPPORT,UPR		1.00	✓ 182.00	23.00	140.14
X PNL,HEADLAMP SUPT,UPR LH		1.00	✓ 58.00	23.00	44.66
X HEADLAMP ASSY,LH		1.00	✓ 1938.00	23.00	1492.26
X HEADLAMP ASSY,RH		1.00	✓ 1938.00	23.00	1492.26
X PANEL,HEADLAMP SUPPORT,LH	→ Supp.	1.00	58.00	23.00	44.66
X REINFORCEMENT,FR BUMPER		1.00	2 490.00	23.00	377.30
X BAR,FR BUMPER GUARD		1.00	130.00	23.00	100.10
X RADIATOR ASSY		1.00	1091.00	23.00	840.07
X CONDENSER ASSY,A/C REFRIGE		1.00	857.00	23.00	659.89
X RIVET,FR BUMPER		6.00	5.00	23.00	23.10
X COVER,ENG ROOM UNDER,FR	} Supp.	1.00	348.00	23.00	267.96
X CLIP,ENG ROOM COVER		20.00	2.00	23.00	30.80
X CLIP,RR BUMPER		20.00	3.00	23.00	46.20
X GARNISH,FR BUMPER SIDE		1.00	✓ 220.00	23.00	169.40
Z TEXT					
AIG OD CLAIM					
DOA : 30.01.21					
SURVEYOR STEVE LKK 02.02.21					
POLICY NO : 1900099739					
Guarantee Your Warranty, Maintain with Cycle & Carriage!					

Parts	9,718.94	Nett	14,158.94
Labour	4,930.00	7% GST on	991.13
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00	Total Payable	15,150.07
Sundry/Others	-540.00		
Total(w/o GST)	14,158.94		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMM 7878 R

<u>Materials</u>		<u>Cost (\$)</u>
1	Panel, headlamp support, LH	58.00 / BT
2	Rivet, front bumper (x6)	30.00 / nec
3	Cover, eng room under, Fr	348.00 / BR
4	Clips (x20)	40.00 / nec
5	Clips (x20)	60.00 / nec
Total		536.00
Less 23% discount		123.28
Total after discount		412.72
7% GST		28.89
Grand total		<u>\$ 441.61</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

SMIFOR

date von PWT-3x vor mit to Base all the card
by 2/21.

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

2021.02.08

All DTCs

2021.02.08

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs		
	Auto Stop & Go (AS&G)	ASG_25080000		No DTCs		
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs		
	AUTO CRUISE	GAS_0E640000		Non-target System		
	4WS/Electric Power Steering	EPS_45880040		No DTCs		
	ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs		
	SRS-AIR BAG	ORC_81047302		No DTCs		
	Air Conditioner	AC_80080011		No DTCs		
	ETACS	ETACS_83040801		No DTCs		
	Meter	MTR_84084001		No DTCs		
	Steering Angle Sensor	GS_SAS_47000100		Non-target System		
	AND	AND_8C080002		Non-equipped System or Communication Error		
	AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
	LIN	ETACS_83040801		Non-target System		
	Power Gate	ETG_92080000		Non-equipped System or Communication Error		

3/3