

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0074/2021/NS
DATE : 21-Jan-21
WIP : 12340

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : YP 6491 X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS LOW POOI FONG
ADDRESS : 57 HUME AVENUE
#09-12
SINGAPORE 598753
TELEPHONE : HP +65 97562680
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100365393-06
VEHICLE NO : **SFP 3193 B**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 25/2/2014
ENGINE NO : CX5 052756
CHASSIS NO : WAUZZZ8V0E1014142
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jan-21
PLACE OF ACCIDENT : IN FRONT OF 285A BUKIT BATOK EAST AVE 3



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFP 3193 B

<u>S/N</u>	<u>NATURE OF JOBS</u>	<u>ESTIMATED CHARGES</u>	<u>SURVEYOR'S RECOMMENDATIONS</u>
1	TO INSTALL SOLAR FILM ON RHS FRONT DOOR WINDOW GLASS.	S/N \$ 400.00	✓
2	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$ 280.00	✓
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 * 250	
4	TO RESPRAY RHS FRONT DOOR, RHS WING MIRROR COVER, RHS FRONT FENDER.	\$ 2,400.00 700	550 + 150 = 700
5	TO TOW VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00	* ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>4,602.00</u>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFP 3193 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 EXTERIOR MIRROR MOUNTING - RH <i>cut</i>		\$ 1,024.00	✓
2 MIRROR CAP - RH <i>Reps</i>		\$ 169.00	+
3 MIRROR GLASS - RH <i>Missing</i>		\$ 1,687.00	✓
4 FRONT DOOR WINDOW - RH <i>cut</i>		\$ 231.00	✓
5 FRONT WINDOW SLOT SEAL - RH <i>cut</i>		\$ 309.00	✓
6 CORNER TRIM - RH <i>Not in</i>		\$ 46.00	X
7 SUNDRIES <i>?</i>		\$ 200.00	?
TOTAL SPARE PARTS	:	\$ 3,666.00	
TOTAL LABOUR CHARGES	:	\$ 4,602.00	
GRAND TOTAL	:	\$ 8,268.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *28/01/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT