

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0101/2021/KS
DATE : 30-Jan-21
WIP : 13240

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/2/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR VADHER HARISH JERAM
ADDRESS : 405 PASIR PANJANG ROAD
SINGAPORE 117634
TELEPHONE : HP +65 93232164
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100480189-04
VEHICLE NO : **SLF 3876 X**
MODEL CODE : Q5 2.0 TFSI QUATTRO
MODEL YEAR : 24/8/2016
ENGINE NO : CNC 167897
CHASSIS NO : WAUZZZ8RXGA134200
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jan-21
PLACE OF ACCIDENT : NEAR NORTH BUONA VISTA RD, SINGAPORE
CORNER OF AYER GAJAH AVENUE/NORTH BUONA VISTA RD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE, SMS 4652 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BONNET.	\$ 4,100.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>7,572.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 3876 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Del</i>	1	\$ 2,724.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 276.00	+
3	FRONT BUMPER SPOILER ?	1	\$ 624.00	?
4	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 210.00	+
5	FRONT BUMPER REINFORCEMENT FOAM ?	1	\$ 114.00	?
6	FRONT BUMPER PULL STRAP <i>new</i>	4	\$ 206.00	+
7	FRONT BUMPER SECURING STRIP - LOWER ?	1	\$ 37.00	?
8	FRONT BUMPER BOTTOM COVER <i>new</i>	1	\$ 127.00	X
9	FRONT BUMPER AIR GUIDE GRILLE LH / RH <i>LH Del</i>	2	\$ 702.00	351
10	FRONT REINFORCEMENT BEAM ?	1	\$ 708.00	?
11	FRONT REINFORCEMENT BEAM SUPPORT LH / RH ?	1	\$ 60.00	?
12	FRONT BUMPER GUIDE SECTION LH - INNER <i>new</i>	1	\$ 38.00	+
13	FRONT BUMPER TOP COVER ?	1	\$ 65.00	+
14	"CAUTION" SIGN STICKER <i>new</i>	1	\$ 14.00	+
15	AIR COND STICKER	1	\$ 8.00	+
16	SIGNAL HORN - LH <i>new</i>	1	\$ 201.00	+
17	SIGNAL HORN BRACKET - LH <i>new</i>	1	\$ 25.00	+
18	FRONT PARKING AID SENSOR <i>new</i>	2	TBC	+
19	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	1	\$ 6.00	+
20	RADIATOR GRILLE <i>Cracked</i>	1	\$ 1,918.00	✓
SUB TOTAL SPARE PARTS		:	\$ 8,063.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 3876 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	"QUATTRO" EMBLEM FOR RADIATOR GRILLE <i>Ne</i>	1	\$ 106.00	✓
22	RADIATOR GRILLE STRIKER PLATE ?	1	\$ 131.00	?
23	BONNET <i>Ne u</i>	1	\$ 4,058.00	+
24	BONNET ATTACHMENT PARTS } <i>Ne u</i>	1	\$ 144.00	+
25	BONNET HINGE LH / RH	2	\$ 206.00	+
26	BONNET CATCH HOOK	1	\$ 140.00	+
27	BONNET EDGE PROTECTION	1	\$ 28.00	+
28	BONNET LOCK WITH MICRO - SWITCH	1	\$ 214.00	+
29	BONNET LOCK WITH MICRO - SWITCH COVER	1	\$ 23.00	+
30	HEADLIGHT MOUNTING LH	1	\$ 118.00	+
31	HEADLIGHT RETAINING PLATE LH	1	\$ 78.00	+
32	HEADLIGHT LH	1	\$ 2,721.00	+
33	HEADLIGHT WASHER LIFT CYLINDER LH	1	\$ 204.00	+
34	HEADLIGHT WASHER LIFT CYLINDER HOSE	1	\$ 182.00	+
35	RADIATOR GRILLE AIR GUIDE LH - INNER ?	1	\$ 25.00	?
36	RADIATOR GRILLE SEALING STRIP - LOWER ?	1	\$ 23.00	?
37	FRONT NO PLATE <i>Deited</i>	S/N	\$ 60.00	✓
38	SUNDRIES ?	1	\$ 200.00	?
TOTAL SPARE PARTS		:	\$ 16,724.00	
TOTAL LABOUR CHARGES		:	\$ 7,572.00	
GRAND TOTAL		:	\$ 24,296.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NAME : Adnan Ling
SURVEYED DATE : 02/02/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : ~~Ata~~ Not Authorised, 03 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT