

Car-in 9/3/21.

wip: 13240.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Xiao Chen.

Kiam/Choi



Adrian

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 3876 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Del</i>	1	\$	2,724.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$	276.00	+
3	FRONT BUMPER SPOILER ?	1	\$	624.00	?
4	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$	210.00	+
5	FRONT BUMPER REINFORCEMENT FOAM <i>exchanged</i>	1	\$	114.00	✓
6	FRONT BUMPER PULL STRAP <i>new</i>	4	\$	206.00	+
7	FRONT BUMPER SECURING STRIP - LOWER ?	1	\$	37.00	-
8	FRONT BUMPER BOTTOM COVER <i>new</i>	1	\$	127.00	+
9	FRONT BUMPER AIR GUIDE GRILLE LH / RH <i>LH Del</i>	2	\$	702.00	351
10	FRONT REINFORCEMENT BEAM ?	1	\$	708.00	?
11	FRONT REINFORCEMENT BEAM SUPPORT LH / RH ?	1	\$	60.00	?
12	FRONT BUMPER GUIDE SECTION LH - INNER <i>new</i>	1	\$	38.00	+
13	FRONT BUMPER TOP COVER <i>exchanged</i>	1	\$	65.00	+
14	"CAUTION" SIGN STICKER <i>new</i>	1	\$	14.00	+
15	AIR COND STICKER	1	\$	8.00	+
16	SIGNAL HORN - LH <i>new</i>	1	\$	201.00	+
17	SIGNAL HORN BRACKET - LH <i>new</i>	1	\$	25.00	+
18	FRONT PARKING AID SENSOR <i>new</i>	2		TBC	+
19	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	1	\$	6.00	+
20	RADIATOR GRILLE <i>exchanged</i>	1	\$	1,918.00	✓
SUB TOTAL SPARE PARTS			\$	8,063.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian
12/03/21