

AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD
 ROC: 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

Estimation

Date _____
 Vehicle SKE 7510 S
 Make/Model AUDI A5
 Chassis No. WAUZZZ8T8BA053779

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BONNET	1		\$ X un -
2	BONNET LOCK	1		\$ X un -
3	BONNET LOCK CATCH	1	\$ 81.50	\$ X un 81.50
4	BONNET HINGE SET	2	\$ 53.45	\$ X un 106.90
5	BONNET DAMPER SET	2	\$ 102.60	\$ X un 205.20
6	FRONT GRILLE ASSY chrome	1		\$ 487.70
7	FRONT GRILLE LOGO - AUDI	1	\$ 102.00	\$ 102.00
8	HEADLAMP L+R	2	\$ 1480	\$ 4424.00 ✓ 750.00
9	HEADLAMP BALLAST L+R	2		\$ X un -
10	HEADLAMP LOWER BRACKET L+R	2	\$ 172.00	\$ X un 344.00
11	HEADLAMP NOZZLE L+R	2	\$ 197.55	\$ X un 395.10
12	FRONT BUMPER	1		\$ 1004.00
13	FRONT BUMPER NOZZLE COVER L+R	2	\$ 51.70	\$ X un 103.40
14	FRONT BUMPER TOW COVER	1	\$ 47.80	\$ X un 47.80
15	FRONT BUMPER SENSOR SET	4		\$ X } un -
16	FRONT BUMPER FOG LAMP L+R	2		\$ X } un -
17	FRONT BUMPER FOG LAMP CHROME L+R	2		\$ X } un -
18	FRONT BUMPER FOG LAMP GARNISH L+R	2	\$ 173.90	\$ X } un 347.80
19	FRONT BUMPER RETAINER L+R	2	\$ 91.40	\$ X un 182.80
20	FRONT BUMPER REINFORCEMENT BAR	1		\$ 516.30
21	FRONT BUMPER SPONGE	1	\$ 221.45	\$ 221.45
22	FRONT BUMPER UNDERCOVER	1	\$ 351.80	\$ X un 351.80
23	FRONT FENDER COWLING RH	1		\$ X un -
24	FRONT SUPPORT PANEL	1		\$ X un -
25	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 342.90	\$ X un 342.90
26	AIRCON CONDENSOR	1	\$ 1,356.70	\$ X un 1,356.70
27	AIRCON CONDENSOR AIRGUIDE L+R	2	\$ 142.65	\$ X un 285.30
28	WIPER WASHER TANK	1	\$ 182.30	\$ X un 182.30
29	FRONT HORN L+R	2	\$ 79.80	\$ X un 159.60
	Airguide in ✓			949.00
			Total	\$ 4816.55
			Less 5%	\$ 240.83
			Total	\$ 4,104.90
				4032.45
				3570.83
				3821.33
				3830.82

S/Nett Items		Unit	Unit Price	Amount
1	FRONT BUMPER CLIPS	1	\$ 100.00	\$ 30 net 100.00
2	FRONT GRILLE GARNISH - QUATTRO	1	\$ 800.00	\$ X un 800.00

3	FRONT NUMBER PLATE	1	\$ 120.00	\$ X	120.00
4	FRONT FENDER COWLING CLIPS	1	\$ 100.00	\$ X	100.00
5	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1	\$ 100.00	\$ X	100.00
			Total	\$	1,220.00

3.0

LABOUR					
1	PANEL BEATING ON AFFECTED AREAS	1	1000	\$ 300	1,000.00
2	SPRAY PAINT ON AFFECTED AREAS	1	800	\$ 300	800.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$ 30	150.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	1	150	\$ X	150.00
5	TO RNR INNER TRIM AND UPHOISTERY	1	600	\$ X	600.00
6	TO CHECK WATER LEAK	1	150	\$ X	150.00
7	TO RNR INNER TRIM AND UPHOISTERY	1	600	\$ X	600.00
8	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	1	300	\$ X	300.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	1000	\$ 180	1,000.00
10	TO RNR FRONT PARKING SENSOR AND CHECK FUNCTION	1	150	\$ X	150.00
11	TO PERFORM RUST PROOFING	1	400	\$ X	400.00
12	TO RNR HORN AND TEST FUNCTION	1	150	\$ X	150.00
			Total	\$	4,750.00

310

Parts Replacement Amount	\$	5,324.90
Total Amount For Labour	\$	4,750.00
Total Amount	\$	10,074.90

Tanfah 17495749
 WP 3/2/21 05 pm

13,401.33

1/5 Resurvey after repair
 tanfah@lkharts.com
 03 days

R = 4
 -S/ = 4
 4/0 = 4
 2 = 4
 7 = 4
 2 = 4

3821.33

~~2870.82~~
 30
 -810

4661.33

~~4670.82~~
 4/5 3750
 03 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: