

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5895K**AAD2102-001***Not Authorised**Resurvey B4 paint**4081-75*~~28 JAN 2021~~

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

02 FEB 2021

SHD5895K

JTDKB3FUX03077066

TOYOTA

PRIUS

29.1.2021

AUTO & GENERAL

4/12/2018

	PART
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	SEAL, REAR BUMPER SIDE, LH
1	RETAINER, REAR BUMPER SIDE, LH
1	RETAINER, REAR BUMPER SIDE, RH
1	FILLER, REAR BUMPER EXTENSION, LH
1	FILLER, REAR BUMPER EXTENSION, RH
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	BOARD ASSY, BACK DOOR TRIM
1	WEATHERSTRIP, BACK DOOR
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH
1	PANEL SUB-ASSY, BACK DOOR
1	LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)
1	LENS AND BODY, REAR LAMP, LH (LOWER)
	LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)
	LENS AND BODY, REAR LAMP, RH (LOWER)
1	COVER, FLOOR UNDER, NO.1 LH
1	COVER, FLOOR UNDER, NO.2 RH
1	COVER, REAR FLOOR CTR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	COVER, FRONT BUMPER
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	REINFORCEMENT, FRONT BUMPER, NO.2
1	ABSORBER, FRONT BUMPER, LOWER

	LIST
\$	Bu 442.60 ✓
\$	R 332.70 X
\$	Sn 15.40 X
\$	Ref/Int 576.30 ✓
\$	Sn 88.50 X
\$	Dis 116.50 ✓
\$	Sn 117.70 X
\$	mgem 123.70 ✓
\$	Sn 124.70 X
\$	R 925.60
\$	Sn 259.20
\$	Sn 372.30
\$	Sn 56.50
\$	R 1,147.80 } X
\$	Sn 443.30
\$	Sn 502.00
\$	Sn 451.80
\$	Sn 502.00
\$	Sn 175.10
\$	Sn 241.90
\$	Sn 229.90
\$	R 650.30
\$	Bu 516.00 ✓
\$	Sn 103.40 X
\$	R 716.60 X
\$	R 246.10 X
\$	Sn 132.70 X

Trans-cab Auto Services Pte Ltd**AAD2102-001**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5895K

1	ABSORBER, FRONT BUMPER ENERGY	\$	Sm	79.60	X
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	Sm	80.10	X
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	Sm	82.30	X
1	STAY SUB-ASSY, FRONT BUMPER, LH	\$	M	47.50	X
1	STAY SUB-ASSY, FRONT BUMPER, RH	\$	M	47.50	X
1	BRACKET, FRONT BUMPER SIDE, LH	\$	Sm	59.30	X
1	BRACKET, FRONT BUMPER SIDE, RH	\$	Sm	59.30	X
1	EXTENSION, FRONT BUMPER, RH	\$	M	120.10	X
1	EXTENSION, FRONT BUMPER, LH	\$	M	120.10	X
1	COVER, FRONT BUMPER HOLE, LH	\$	Sm	29.30	X
1	COVER, FRONT BUMPER HOLE, RH	\$	Sm	29.30	X
1	LAMP ASSY, FOG, LH	\$	Sm	951.40	X
1	LAMP ASSY, FOG, RH	\$	Sm	951.40	X
1	UNIT ASSY, HEADLAMP, LH	\$	Sm	2,637.60	X
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	Sm	960.50	X
1	UNIT ASSY, HEADLAMP, RH	\$	Sm	2,637.60	X
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	Sm	960.50	X
1	GRILLE SUB-ASSY, RADIATOR	\$	M	346.00	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	Sm	170.10	X
1	EMBLEM ASSY, RADIATOR GRILLE	\$	M	90.80	—

TOTAL	\$	20,070.90
25%	\$	5,017.73
	\$	15,053.18

Special Nett

1SET PARKING AID	\$	M	700.00	2705M—
1SET REAR BUMPER CLIP	\$	M	95.00	505M—
2 WINDSCREEN SEALANT	\$	M	150.00	805M—
1 WINDSCREEN MOULDING	\$	M	200.00	—
1 WINDSCREEN INNER SPONGE SEAL	\$	M	130.00	305M—
1 REAR TAILGATE TOYOTA LOGO	\$	M	47.90	—
1 REAR TAILGATE WORDING 'PRIUS'	\$	M	54.60	—
1 REAR TAILGATE WORDING 'HYBRID'	\$	M	54.60	—
1 REAR TAILGATE STICKER "Trans-Cab"	\$	M	80.00	305M—
1 REAR TAILGATE STICKER "6555-3333"	\$	M	80.00	305M—

} 25%

Trans-cab Auto Services Pte Ltd**AAD2102-001**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5895K

1 REAR BUMPER PROTECTOR	\$	<i>NLP</i>	180.00	X
2 SEAM SEALANT	\$	<i>nn</i>	250.00	X
1SET REAR BUMPER RETAINER CLIP	\$	<i>nn</i>	85.00	X
1 FRONT NUMBER PLATE WITH HOLDER	\$	<i>B</i>	140.00	<i>45mm</i>
1SET TAILLAMP LOWER CLIP	\$	<i>nn</i>	55.00	X
1SET TAILLAMP UPPER CLIP	\$	<i>nn</i>	55.00	X
1 END PANEL TRIM CLIP	\$	<i>nn</i>	65.00	X
1 REAR SPOILER CLIP	\$	<i>nn</i>	70.00	X
1SET BUMPER CLIP FRT	\$	<i>nn</i>	95.00	<i>50mm</i>
1 REAR NUMBER PLATE WITH MOULDING	\$	<i>sn</i>	200.00	X
1SET FRT BUMPER RETAINER CLIP	\$	<i>nn</i>	85.00	X

TOTAL	\$	2,872.10
--------------	-----------	-----------------

TOTAL PARTS	\$	17,925.28
--------------------	-----------	------------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$	300.00	<i>1800</i>
----	--------	-------------

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$	<i>nn</i>	380.00	X
----	-----------	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	2,800.00	<i>6000</i>
----	----------	-------------

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	<i>nn</i>	380.00	X
----	-----------	--------	---

To transfer of Rear Door fittings, attachments and perform water seepage test.

\$	180.00	<i>600</i>
----	--------	------------

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$	<i>nn</i>	480.00	X
----	-----------	--------	---

Trans-cab Auto Services Pte Ltd**AAD2102-001**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5895K

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,800.00	6601
To reinstall rear bumper parking sensor.	\$		170.00	501
To Check Electrical Lighting Concerned.	\$		170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	220.00	X
To replace, refix and top up coolant for radiator	\$	nn	170.00	X
To lift-up / out engine with gear box and refit.	\$	nn	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	nn	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn	380.00	X

TOTAL \$ 10,480.00**Over All Total \$ 28,405.28**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- (PART-BY-PART) Repair Days

~~14 DAYS~~
4 days

Acknowledged by Repairer

Signature:

Date: