

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SG LEASING PTE LTD
15 YISHUN INDUSTRIAL ST 1 #01-08
SINGAPORE 768091

TP Chim.
Veron.

Contact : 84211426, 98526606

ESTIMATE

Repair Code : CLM16687
Date in : 01/02/2021
Vehicle Num. : GBC3481K
Model : NISSAN NV200 1.5L MT ABS AIRBAG 2WD 6DR
Chassis/Eng# : VSKYBAM20U0025369/K9KF276D123531

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehd</i>	1	700.80	✓ 700.80
REAR BUMPER REFLECTOR L/R <i>LH could, RH Missing</i>	2	61.90	✓ 123.80
REAR BUMPER SIDE RETAINER L/R <i>nu</i>	2	37.20	✓ 74.40
REAR BUMPER SPONGE <i>could</i>	1	94.00	✓ 94.00
REAR BUMPER TOW HOOK COVER <i>ut</i>	1	15.00	✓ 15.00
REAR END PANEL TOP GARNISH <i>could</i>	1	83.90	✓ 83.90
REAR LH TAILGATE <i>Dented</i>	1	1469.60	✓ 1,469.60
REAR LH TAILGATE 'LOGO' EMBLEM <i>3 nlu</i>	1	64.90	✓ 64.90
REAR LH TAILGATE 'NV200' EMBLEM	1	136.00	✓ 136.00
REAR LH TAILGATE HINGE (LOWER) <i>not Bent</i>	1	107.20	✓ 107.20
REAR LH TAILGATE MECHANISM LOCK (LOWER) <i>Dented</i>	1	115.90	✓ 115.90
REAR LH TAILGATE MECHANISM LOCK (TOP) <i>Damaged</i>	1	108.90	✓ 108.90
REAR LH TAILGATE OUTER HANDLE <i>could</i>	1	352.00	✓ 352.00
REAR RH TAILGATE <i>Dented</i>	1	1102.20	✓ 1,102.20
REAR RH TAILGATE 'CDI' EMBLEM <i>nu</i>	1	130.80	✓ 130.80
REAR RH TAILGATE HINGE (LOWER) <i>Bent</i>	1	107.20	✓ 107.20
REAR RH TAILGATE MECHANISM LOCK (LOWER) <i>3 nlu</i>	1	115.90	✓ 115.90
REAR RH TAILGATE MECHANISM LOCK (TOP)	1	108.90	✓ 108.90

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SG LEASING PTE LTD
 15 YISHUN INDUSTRIAL ST 1 #01-08
 SINGAPORE 768091

Contact : 84211426, 98526606

ESTIMATE

Repair Code : CLM16687
 Date in : 01/02/2021
 Vehicle Num. : GBC3481K
 Model : NISSAN NV200 1.5L MT ABS AIRBAG 2WD 6DR
 Chassis/Eng# : VSKYBAM20U0025369/K9KF276D123531

REAR RH TAILGATE WEATHER (VERTICAL) <i>ut</i>	1	72.60	✓	72.60
REAR SPARE TYRE CARRIAGE	1	297.30	✗	297.30
REAR SPARE TYRE CARRIAGE BRACKET <i>green</i>	1	69.30	✗	69.30
REAR TAILGATE WEATHER STRIP <i>ut</i>	1	88.90	✓	88.90
REAR TAILLAMP L/R <i>cracked</i>	2	277.20	✓	554.40
Subtotal before discount				6,093.90
Percentage discount 10%				609.39
Sub-total 1				5,484.51
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	<i>30</i> 80.00	
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	280.00	<i>20</i> 280.00	
REAR END PANEL (OUTER) <i>Dented</i>	1	150.00	✓	150.00
REAR END PANEL TOP GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>10</i> 40.00	
REAR LH TAILGATE '70KM' STICKER <i>new</i>	1	25.00	<i>15</i> 25.00	
REAR LH TAILGATE NUMBER PLATE <i>new</i>	1	25.00	+	25.00
REAR LH TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	+	50.00
REAR LH TAILGATE OUTER HANDLE CLIPS - SET <i>new</i>	1	30.00	<i>20</i> 30.00	
REAR LH TAILGATE WINDSCREEN SEAL <i>green</i>	1	90.00	<i>50</i> 90.00	
REAR LH TAILGATE WINDSCREEN SEALANT	1	80.00	<i>60</i> 80.00	

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SG LEASING PTE LTD
15 YISHUN INDUSTRIAL ST 1 #01-08
SINGAPORE 768091

Contact : 84211426, 98526606

ESTIMATE

Repair Code : CLM16687
Date in : 01/02/2021
Vehicle Num. : GBC3481K
Model : NISSAN NV200 1.5L MT ABS AIRBAG 2WD 6DR
Chassis/Eng# : VSKYBAM20U0025369/K9KF276D123531

REAR RH TAILGATE WINDSCREEN SEAL	645	1	90.00	50	90.00
REAR RH TAILGATE WINDSCREEN SEALANT		1	80.00	60	80.00
Subtotal before discount					1,020.00
Percentage discount 0%					0.00
Sub-total 2					1,020.00
Parts-total					6,504.51

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall tailgate windscreen
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.
- To remove, reinstall tailgate mechanism and check for function

80 ~~100.00~~
160 ~~300.00~~
60 ~~120.00~~
1000 ~~1,300.00~~
1200 ~~1,400.00~~
60 ~~120.00~~
100 ~~140.00~~

Labour Total

3,480.00

Parts & Labour Total

9,984.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer generated document which requires no signature.***

page 3

Adrian L
h/s 03/02/21

08 Days

Total: 8459.57

h/s: 6.7K ✓