

Our Job Ref No : 305451673
Date : 21.02.21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHC358H CCPL

02.02.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **AIG** **SMR9212Y**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$1,250.00

Final Lumpsum Repair cost **\$1,250.00**

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 6/3/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305451673
 REGN NO : SHC 358H
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 13.09.2017
 DATE/TIME IN : 02.02.2021 11:35
 ACCIDENT DATE : 02.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2282-G	COVER REAR BUMPER%	1 L	458.60	25.00	343.95	de	
0002	04-01-0302-2267-G	BUMPER PIECE	10 L	22.00	25.00	16.50	net	
0003	04-01-0302-2287-G	GUARD-REAR BUMPER CENTER	1 L	552.60	25.00	414.45	de	1,033.20
0004	04-01-0302-1150-A	BUMPER PROTECTOR MAT	1 N	50.00	2.50	50.00	net	-25%
0005	09-01-0302-2005-A	REVERSE SENSOR ASSY	1 N	135.70	0.25	135.70	net	774.90
								+ Net 185.70
								960.60
								SUB-TOTAL : 960.60

JOB NATURE

0000	L	PANEL BEATING	400.00	350		630
0001	23-502	SPRAYPAINT ON AFFECTED AREA	300.00	250		1,590.60
0002	L	REMOVE/REFIX REVERSE SENSOR	80.00	30		-20%
						1,272.48
						SUB-TOTAL : 780.00

Tamplin 9749 5747

WP / 2/2/21 @ 5pm

4/5 Resurvey after repair \$1,250/-

Tamplin @ 16hantoon

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: