



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Ref: CC4/ASM21001574/Kba3q2 Date: 15/04/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 9329T	Veh. Inspected	SKW 5548C	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S1M033YH	Excess (\$)	0.00	
Assign From		Assign Date	02/02/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHDH41CMGU655430	Colour	METALLIC SILVER	
Odometer	90075 KM	Steering	JAMMED	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	5 mm	
L/H Front Tyre	205/55 R16	PIRELLI	5 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/01/2021	Inspection Date	02/02/2021	
Survey held at	Stars Autoworks 160 Sin Ming Drive, Sin Ming AutoCity. #06-21 Singapore 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	