

Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 849k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 7-9 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

67A Rb 833,181.00

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS. \$ _____

Fees:

Others

TOTAL

Veh No: SKT 970IRYr Regn: 06, 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Qashgarc.c. 1197Colour: M. GreyA/C: Insured / Std / NI / NASp. Reading: 120 683T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STNFEAT114.1400999Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 29/1/21D.O.I. 2/2/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 29/01/2021

TP Veh Reg No: CB6351B

Estimate No: ES2100013

Date: 01 Feb 2021

Policy No:

Veh Reg No: SKT9701R

Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
5DR

Chassis No: SJNFEAJ11U1400999

Engine No: HRA2512750A

Reg. Date: 26/06/2015

Estimate Repair Cost to Vehicle No :SKT9701R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00	45.00
2 REAR WINDSCREEN SEALANT	60.00	1 PC	60.00	40.00
3 REVERSE CAMERA	252.00	1 PC	252.00	X
4 REVERSE SENSOR CENTRE - LH	270.00	1 PC	270.00	✓
5 REVERSE SENSOR CENTRE - RH	270.00	1 PC	270.00	✓
6 REVERSE SENSOR CORNER - LH	270.00	1 PC	270.00	?
7 REVERSE SENSOR CORNER - RH	270.00	1 PC	270.00	X
			1,452.00	1,452.00
Spare Parts				
8 FRONT BONNET	1,061.30	1 PC	1,061.30	X
9 FRONT BONNET RUBBER	55.00	1 PC	55.00	X
10 FRONT BUMPER	872.90	1 PC	872.90	✓
11 FRONT BUMPER CLIPS	60.00	1 SET	60.00	✓
12 FRONT BUMPER SIDE RETAINER - LH	83.50	1 PC	83.50	✓
13 FRONT BUMPER SIDE RETAINER - RH	83.50	1 PC	83.50	✓
14 FRONT FENDER - RH	507.96	1 PC	507.96	X
15 FRONT GRILLE	525.00	1 PC	525.00	?
16 FRONT GRILLE CHROME	320.15	1 PC	320.15	?
17 FRONT GRILLE LOGO	285.15	1 PC	285.15	?
18 FRONT HEADLAMP - LH	955.50	1 PC	955.50	X
19 FRONT HEADLAMP - RH	955.50	1 PC	955.50	✓
20 FRONT HEADLAMP LOWER BRACKET	185.15	1 PC	185.15	?
21 FRONT SUPPORT PANEL (TOP)	588.10	1 PC	588.10	X
22 FRONT SUPPORT PANEL TOP GARNISH	320.15	1 PC	320.15	X
23 FRONT SUPPORT PANEL TOP GARNISH CLIPS	50.00	1 SET	50.00	X
24 REAR AIR VENT - LH	60.50	1 PC	60.50	?
25 REAR BUMPER	1,212.75	1 PC	1,212.75	✓
26 REAR BUMPER BRACKET - LH	118.98	1 PC	118.98	?
27 REAR BUMPER BRACKET - RH	118.98	1 PC	118.98	?
28 REAR BUMPER CENTRE PAD	593.10	1 PC	593.10	✓
29 REAR BUMPER CLIPS	50.00	1 SET	50.00	✓
30 REAR BUMPER LOWER GARNISH 'SILVER'	346.95	1 PC	346.95	?
31 REAR BUMPER REFLECTOR - LH	141.39	1 PC	141.39	X
32 REAR BUMPER REFLECTOR - RH	141.39	1 PC	141.39	X
33 REAR BUMPER SIDE RETAINER - LH	70.50	1 PC	70.50	✓



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 29/01/2021
TP Veh Reg No: CB6351B

Estimate No: ES2100013
Date: 01 Feb 2021
Policy No:
Veh Reg No: SKT9701R
Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
5DR
Chassis No: SJNFEAJ11U1400999
Engine No: HRA2512750A
Reg. Date: 26/06/2015

Estimate Repair Cost to Vehicle No :SKT9701R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
34 REAR BUMPER SIDE RETAINER - RH	70.50	1 PC	70.50	✓
35 REAR BUMPER TOWING COVER - RH	60.00	1 PC	60.00	X
36 REAR BUZZER SENSOR	170.00	1 PC	170.00	?
37 REAR ELECTRONICS ANTENNA SENSOR	178.00	1 PC	178.00	?
38 REAR END PANEL INNER	504.80	1 PC	504.80	?
39 REAR END PANEL INNER GARNISH	253.71	1 PC	253.71	?
40 REAR END PANEL LOWER GARNISH	259.20	1 PC	259.20	X
41 REAR END PANEL OUTER	792.05	1 PC	792.05	?
42 REAR END PANEL TOP GARNISH	288.90	1 PC	288.90	?
43 REAR FENDER INNER TRIMBOARD - LH	772.38	1 PC	772.38	X
44 REAR FENDER INNER TRIMBOARD - RH	772.38	1 PC	772.38	X
45 REAR INNER TRIM SIDE COVER - LH	166.50	1 PC	166.50	X
46 REAR INNER TRIM SIDE COVER - RH	166.50	1 PC	166.50	X
47 REAR NUMBER PLATE LAMP - LH	92.16	1 PC	92.16	X
48 REAR NUMBER PLATE LAMP - RH	92.16	1 PC	92.16	X
49 REAR SPARE WHEEL PANEL	855.80	1 PC	855.80	X
50 REAR TAIL LAMP - LH	653.58	1 PC	653.58	X
51 REAR TAIL LAMP - RH	653.58	1 PC	653.58	X
52 REAR TAILGATE	1,625.49	1 PC	1,625.49	✓
53 REAR TAILGATE ABSORBER - LH	198.45	1 PC	198.45	X
54 REAR TAILGATE ABSORBER - RH	198.45	1 PC	198.45	X
55 REAR TAILGATE EMBLEM 'LOGO'	85.60	1 PC	85.60	✓
56 REAR TAILGATE EMBLEM 'Qashqai'	113.31	1 PC	113.31	✓
57 REAR TAILGATE INNER HOLDER	55.89	1 PC	55.89	X
58 REAR TAILGATE INNER TRIMBOARD	558.09	1 PC	558.09	X
59 REAR TAILGATE LOCK	410.31	1 PC	410.31	?
60 REAR TAILGATE LOCK COVER	53.37	1 PC	53.37	X
61 REAR TAILGATE OUTER GARNISH	288.15	1 PC	288.15	?
62 REAR TAILGATE OUTER OPENING SWITCH	166.95	1 PC	166.95	X
63 REAR TAILGATE REFLECTOR - LH	772.38	1 PC	772.38	X
64 REAR TAILGATE REFLECTOR - RH	772.38	1 PC	772.38	X
65 REAR TAILGATE WEATHERSTRIP	212.31	1 PC	212.31	X
66 REAR TAILGATE WIPER MOTOR	436.95	1 PC	436.95	X
67 REAR WHEEL PANEL TOOL BOX	410.58	1 PC	410.58	X
68 REAR WHEEL PANEL TRIMBOARD	459.00	1 PC	459.00	X
69 REAR WINDSCREEN MOULDING	120.96	1 PC	120.96	✓
70 REAR WINDSCREEN SOLAR FILM	252.00	1 PC	252.00	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9887 4031

Email: yeeautopteLtd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 29/01/2021
TP Veh Reg No: CB6351B

Estimate No: ES2100013
Date: 01 Feb 2021
Policy No:
Veh Reg No: SKT9701R
Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
5DR
Chassis No: SJNFEAJ11U1400999
Engine No: HRA2512750A
Reg. Date: 26/06/2015

Estimate Repair Cost to Vehicle No :SKT9701R

Description	U/Price	Quantity	List Price	Amount
71 REAR WIPER BLADE	60.20	1 PC	60.20	60.20
72 REAR WIPER MOTOR	511.38	1 PC	511.38	511.38
73 SPARE WHEEL TOP COVER	346.63	1 PC	346.63	346.63
			24,674.43	24,674.43
Labour				
74 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,000.00	1 JOB	2,000.00	2,000.00
75 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,300.00	1 JOB	2,300.00	2,300.00
76 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	200.00
77 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	200.00
78 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	80.00	1 JOB	80.00	80.00
79 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	80.00
80 COMPUTER DIAGNOSTIC RESET	280.00	1 JOB	280.00	280.00
81 TO TOW VEHICLE TO WORKSHOP.	120.00	1 JOB	120.00	120.00
			5,260.00	5,260.00

Total S\$ 31,386.43

Add GST @ 7% 2,197.05

Total Amount Payable S\$ 33,583.48

TOTAL: SINGAPORE DOLLAR THIRTY THREE THOUSAND FIVE HUNDRED EIGHTY THREE AND CENTS FORTY EIGHT ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/01/2021 16:14 (SGT)
Date of Accident 29/01/2021 07:20 (SGT)
Exact Location of Accident BKE, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKT9701R

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner Yak Joon Ming
NRIC No SXXXX231A
Email Address jm_yak@yahoo.com.sg
Mobile Phone No (Phone) +65-96631579
Alternative Phone No +65-96631579

VEHICLE PARTICULARS

Manufacturer Nissan
Model Qashqai
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 2100419686-05
Cover Note Number -

DRIVER

Name of Driver Yak Joon Ming
NRIC No SXXXX231A
Date Of Birth 30/04/1967
Occupation Indoor

Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

13/01/1988
35 YEARS
Male
(Phone) +65-96631579
+65-96631579
jm_yak@yahoo.com.sg
Blk 313A Anchorvale Road #14-124

541313

Yes

No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Chain Collision

Clear

Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No

4

No

-

Yes

1

No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No

No

-

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes

No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name

CB6351B

-

-

-

-

Commercial vehicle

-

-

-


-

-

-

SKETCH PLAN

(A) SKT9701R (B) CB6351B (C) SMF8733E (D) SL8874D



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/1/21 at 7:20am I was travelling my vehicle (A) SKT9701R along BKE towards KSE. The traffic was heavy, in front of my vehicle move slowly and stop. I also stop. Suddenly the vehicle (B) CB6351B cannot stop in time hit my vehicle rear portion. The impact force my vehicle move forward and hit onto vehicle (C) SMF8733E. I go down and check there was 4 cars chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

29 JAN 2021

Driver's Signature

(If driver is not the policyholder)

Date & Time:

29 JAN 2021

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim