



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteitd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

N: Motor Claim Department

Ref No: -
 m Type: Third Party
 ident Date: 29/01/2021
 Veh Reg No: CB6351B

Estimate No: ES2100013
 Date: 01 Feb 2021
 Policy No:
 Veh Reg No: SKT9701R
 Make/Model: NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
 Chassis No: SJNFEAJ11U1400999
 Engine No: HRA2512750A
 Reg. Date: 26/06/2015

Not Authorized
L1 Reg & 6900h
Recovery After Paint
7 days

Estimate Repair Cost to Vehicle No :SKT9701R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
REAR NUMBER PLATE	60.00	1 PC	60.00	45.50
REAR WINDSCREEN SEALANT	60.00	1 PC	60.00	40.50
REVERSE CAMERA	252.00	1 PC	252.00	X
REVERSE SENSOR CENTRE - LH	270.00	1 PC	270.00	X
REVERSE SENSOR CENTRE - RH	270.00	1 PC	270.00	X
REVERSE SENSOR CORNER - LH	270.00	1 PC	270.00	X
REVERSE SENSOR CORNER - RH	270.00	1 PC	270.00	X
			1,452.00	1,452.00
Spare Parts				
FRONT BONNET	1,061.30	1 PC	1,061.30	X
FRONT BONNET RUBBER	55.00	1 PC	55.00	X
FRONT BUMPER	872.90	1 PC	872.90	X
FRONT BUMPER CLIPS	60.00	1 SET	60.00	X
FRONT BUMPER SIDE RETAINER - LH	83.50	1 PC	83.50	X
FRONT BUMPER SIDE RETAINER - RH	83.50	1 PC	83.50	X
FRONT FENDER - RH	507.96	1 PC	507.96	X
FRONT GRILLE	525.00	1 PC	525.00	X
FRONT GRILLE CHROME	320.15	1 PC	320.15	X
FRONT GRILLE LOGO	285.15	1 PC	285.15	X
FRONT HEADLAMP - LH	955.50	1 PC	955.50	X
FRONT HEADLAMP - RH	955.50	1 PC	955.50	X
FRONT HEADLAMP LOWER BRACKET	185.15	1 PC	185.15	X
FRONT SUPPORT PANEL (TOP)	588.10	1 PC	588.10	X
FRONT SUPPORT PANEL TOP GARNISH	320.15	1 PC	320.15	X
FRONT SUPPORT PANEL TOP GARNISH CLIPS	50.00	1 SET	50.00	X
REAR AIR VENT - LH	60.50	1 PC	60.50	X
REAR BUMPER	1,212.75	1 PC	1,212.75	X
REAR BUMPER BRACKET - LH	118.98	1 PC	118.98	X
REAR BUMPER BRACKET - RH	118.98	1 PC	118.98	X
REAR BUMPER CENTRE PAD	593.10	1 PC	593.10	X
REAR BUMPER CLIPS	50.00	1 SET	50.00	X
REAR BUMPER LOWER GARNISH 'SILVER'	346.95	1 PC	346.95	X
REAR BUMPER REFLECTOR - LH	141.39	1 PC	141.39	X
REAR BUMPER REFLECTOR - RH	141.39	1 PC	141.39	X
REAR BUMPER SIDE RETAINER - LH	70.50	1 PC	70.50	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 29/01/2021
TP Veh Reg No: CB6351B

Estimate No: ES2100013
Date: 01 Feb 2021
Policy No:
Veh Reg No: SKT9701R
Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
5DR
Chassis No: SJNFEAJ11U1400999
Engine No: HRA2512750A
Reg. Date: 26/06/2015

Estimate Repair Cost to Vehicle No :SKT9701R

Description	U/Price	Quantity	List Price	Amount
34 REAR BUMPER SIDE RETAINER - RH	70.50	1 PC	70.50	SS
35 REAR BUMPER TOWING COVER - RH	60.00	1 PC	60.00	X
36 REAR BUZZER SENSOR	170.00	1 PC	170.00	X
37 REAR ELECTRONICS ANTENNA SENSOR	178.00	1 PC	178.00	X
38 REAR END PANEL INNER	504.80	1 PC	504.80	X
39 REAR END PANEL INNER GARNISH	253.71	1 PC	253.71	X
40 REAR END PANEL LOWER GARNISH	259.20	1 PC	259.20	X
41 REAR END PANEL OUTER	792.05	1 PC	792.05	X
42 REAR END PANEL TOP GARNISH 65.00	288.90	1 PC	288.90	X
43 REAR FENDER INNER TRIMBOARD - LH	772.38	1 PC	772.38	X
44 REAR FENDER INNER TRIMBOARD - RH	772.38	1 PC	772.38	X
45 REAR INNER TRIM SIDE COVER - LH	166.50	1 PC	166.50	X
46 REAR INNER TRIM SIDE COVER - RH	166.50	1 PC	166.50	X
47 REAR NUMBER PLATE LAMP - LH	92.16	1 PC	92.16	X
48 REAR NUMBER PLATE LAMP - RH	92.16	1 PC	92.16	X
49 REAR SPARE WHEEL PANEL	855.80	1 PC	855.80	X
50 REAR TAIL LAMP - LH	653.58	1 PC	653.58	X
51 REAR TAIL LAMP - RH	653.58	1 PC	653.58	X
52 REAR TAILGATE	1,625.49	1 PC	1,625.49	X
53 REAR TAILGATE ABSORBER - LH	198.45	1 PC	198.45	X
54 REAR TAILGATE ABSORBER - RH	198.45	1 PC	198.45	X
55 REAR TAILGATE EMBLEM 'LOGO'	85.60	1 PC	85.60	X
56 REAR TAILGATE EMBLEM 'Qashqai'	113.31	1 PC	113.31	X
57 REAR TAILGATE INNER HOLDER	55.89	1 PC	55.89	X
58 REAR TAILGATE INNER TRIMBOARD	558.09	1 PC	558.09	X
59 REAR TAILGATE LOCK 173.20	410.31	1 PC	410.31	X
60 REAR TAILGATE LOCK COVER	53.37	1 PC	53.37	X
61 REAR TAILGATE OUTER GARNISH	288.15	1 PC	288.15	X
62 REAR TAILGATE OUTER OPENING SWITCH	166.95	1 PC	166.95	X
63 REAR TAILGATE REFLECTOR - LH	772.38	1 PC	772.38	X
64 REAR TAILGATE REFLECTOR - RH	772.38	1 PC	772.38	X
65 REAR TAILGATE WEATHERSTRIP	212.31	1 PC	212.31	X
66 REAR TAILGATE WIPER MOTOR	436.95	1 PC	436.95	X
67 REAR WHEEL PANEL TOOL BOX	410.58	1 PC	410.58	X
68 REAR WHEEL PANEL TRIMBOARD	459.00	1 PC	459.00	X
69 REAR WINDSCREEN MOULDING	120.96	1 PC	120.96	X
70 REAR WINDSCREEN SOLAR FILM 106	252.00	1 PC	252.00	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteitd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 29/01/2021
TP Veh Reg No: CB6351B

Estimate No: ES2100013
Date: 01 Feb 2021
Policy No:
Veh Reg No: SKT9701R
Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
5DR
Chassis No: SJNFEAJ11U1400999
Engine No: HRA2512750A
Reg. Date: 26/06/2015

Estimate Repair Cost to Vehicle No :SKT9701R

Description	U/Price	Quantity	List Price	Amount
71 REAR WIPER BLADE	60.20	1 PC	60.20	60.20
72 REAR WIPER MOTOR	511.38	1 PC	511.38	511.38
73 SPARE WHEEL TOP COVER	346.63	1 PC	346.63	346.63
Labour			24,674.43	24,674.43
74 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,000.00	1 JOB	2,000.00	2,000.00
75 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,300.00	1 JOB	2,300.00	2,300.00
76 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	200.00
77 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	200.00
78 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	80.00	1 JOB	80.00	80.00
79 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	80.00
80 COMPUTER DIAGNOSTIC RESET	280.00	1 JOB	280.00	280.00
81 TO TOW VEHICLE TO WORKSHOP.	120.00	1 JOB	120.00	120.00
			5,260.00	5,260.00
Total				SS 31,386.43
			Add GST @ 7%	2,197.05
			Total Amount Payable	SS 33,583.48

TOTAL: SINGAPORE DOLLAR THIRTY THREE THOUSAND FIVE HUNDRED EIGHTY THREE AND CENTS FORTY EIGHT ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE