

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21001579/BBA3Q2
Date: 14/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMP928K	Insured Vehicle No :	SLN6133U
Date of Loss:	21/01/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP928K		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB6744199
Reg. Date:	02/09/2019 (Man. Year: 2018)	Chassis No:	RU31324188
Colour:	Brown	Odometer:	74040 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,088.56	300.00	5,788.56	95.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,300.00	1,900.00	59.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,288.56	1,600.00	7,688.56	82.77
Approved Total (Overridden) (S\$)		1,300.00		

(S\$)	9,288.56	1,300.00	7,988.56	86.00
+ GST 7.00/7.00% (S\$)	650.20	91.00	559.20	86.00
Nett Amount (S\$)	9,938.76	1,391.00	8,547.76	86.00
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 02/02/2021

Date Inspected: 03/02/2021

Estimated Period of Repair: 4.0 days

Inspected At:

160 SIN MING DRIVE, #01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP928K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	1,280.00 FL	*- FL
2	1		*FRONT DOOR BLACK TAPE RH	Not Necessary	106.00 FL	*- FL
3	1		*FRONT DOOR WEATHERSTRP RH	Not Necessary	194.40 FL	*- FL
4	1		*FRONT DOOR INNER LOCK RH	Not Necessary	523.00 FL	*- FL
5	1		*FRONT DOOR LOCK STRIKER RH	Not Necessary	68.00 FL	*- FL
6	1		*FRONT DOOR TRIMBOARD RH	Not Necessary	683.90 FL	*- FL
7	1		*REAR DOOR RH	Repair	1,280.00 FL	*- FL
8	1		*REAR DOOR BLACK TAPE RH	Not Necessary	106.00 FL	*- FL
9	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	142.10 FL	*- FL
10	1		*REAR DOOR INNER LOCK RH	Not Necessary	328.90 FL	*- FL
11	1		*REAR DOOR LOCK STRIKER RH	Not Necessary	68.00 FL	*- FL
12	2		*REAR DOOR HINGE RH	Not Necessary	164.00 FL	*- FL
13	1		*REAR DOOR CHECKER ARM RH	Not Necessary	102.80 FL	*- FL
14	1		*REAR DOOR FRAME RUBBER RH	Not Necessary	106.90 FL	*- FL
15	1		*REAR DOOR TRIMBOARD RH	Not Necessary	683.90 FL	*- FL
16	1		*SIDE SKIRT RH	Not Necessary	785.30 FL	*- FL
17	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
18	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
19	1		*FRONT DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*FRONT DOOR OUTER CHROME MOULDING	Cut	180.00 FS	*120.00 FS
21	1		*REAR DOOR SEALANT	Not Necessary	100.00 FS	*- FS
22	1		*REAR DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*REAR DOOR OUTER CHROME MOULDING	Cut	180.00 FS	*120.00 FS
24	1		*SIDE SKIRT CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,413.20	300.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,324.64	0.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$)	6,088.56
						300.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R FRONT DOOR COMPONENT	New	150.00	80.00
2	R&R REAR DOOR COMPONENT	New	150.00	80.00
3	CHECK WIRING	New	100.00	60.00
4	UPHOLSTERY	New	300.00	0.00
5	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
6	PANEL BEATING	New	1,000.00	600.00
7	RUST PROOFING	New	200.00	80.00
8	SPRAY PAINTING	New	1,000.00	400.00
Gross Labour Cost (S\$)			3,200.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >