



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving TPVD TOYOTA HIACE (GBH7591Z)

Date of Loss 5 November 2020

Time of Loss 20.10

Loss Description YQ39D (INSD) C/W GBH9591Z (TP)

Comment

Workshop Details

Total Rebate Amount 23889

Nett Loss Amount \$36,111.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion * 20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	GBH7591Z	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>20/09/2018</div> <div></div>
Mileage	<div>129575</div>	Age of Vehicle	2

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2018</div>
Make	TPVD TOYOTA	<div>TOYOTA</div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	MUHMMAAD SYAFIQ BIN TAHAR	<div></div>
Date of Birth	15 December 1986	<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	HIACE POLICY INFORMATION
	HIACE DX 2.8 AUTO
Type	<input type="text"/>
Type of Paint	<input type="text"/>
Chassis No	GDH2012001702
Engine No	1GD8303115
Engine Capacity	2754
Sum Insured	0
Market Value	60000

CATEGORY Age	FNOL INFORMATION 34	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	0	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date		<input type="text"/> 
License Expiration Date		<input type="text"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address		<input type="text"/>
Address type		<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S8636059D	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

04/02/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts











Add













Approve












Deny



Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		TAILGATE	Replaced	0	1785	No		25			1338.75	Reviewing
<input type="checkbox"/>		0	2		TAILGATE HINGE R/L	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	2		TAILGATE SUPPORT STAY R/L	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RR WINDSCREEN	Replaced	0	1120	No		25			840	Reviewing
<input type="checkbox"/>		0	4		TAILGATE WINDSCREEN DAM STOPPER	Replaced	0	9.2	No		25			27.6	Reviewing
<input type="checkbox"/>		0	2		TAILGATE WINDSCREEN SPACER A	Replaced	0	6.3	No		25			9.45	Reviewing
<input type="checkbox"/>		0	2		TAILGATE WINDSCREEN SPACER B	Replaced	0	13.4	No		25			20.1	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	2		TAILGATE WINDSCREEN SPACER CLIP	Replaced	0	10.7	No		25			16.05	Reviewing
<input type="checkbox"/>		0	1		TAILGATE NO. PLATE GARNISH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	2		TAILGATE NO. PLATE LAMP R/L	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TAILGATE REVERSE SENSOR CAMERA	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TAILGATE EMBLEM (LOGO)	Replaced	0	72.2	No		25			54.15	Reviewing
<input type="checkbox"/>		0	1		TAILGATE STICKER (1200KG)	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TAILGATE INNER TRIM BOARD	Replaced	0	181	No		25			135.75	Reviewing
<input type="checkbox"/>		0	10		TAILGATE INNER TRIM CLIP	Replaced	0	3.2	No		25			24	Reviewing
<input type="checkbox"/>		0	1		TAILGATE LOCK OUTER HANDLE	Replaced	0	110.4	No		25			82.8	Reviewing
<input type="checkbox"/>		0	1		TAILGATE LOCK	Replaced	0	276.6	No		25			207.45	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		TAILGATE LOCK COVER	Replaced	0	82.3	No		25			61.73	Reviewing
<input type="checkbox"/>		0	1		TAILGATE LOCK CONTROL	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TAILGATE WEATHERSTRIP	Replaced	0	408.4	No		25			306.3	Reviewing
<input type="checkbox"/>		0	2		TAILLAMP R/L	Replaced	0	306.4	No		25			459.6	Reviewing
<input type="checkbox"/>		0	1		RR BUMPER	Replaced	0	454.3	No		25			340.73	Reviewing
<input type="checkbox"/>		0	6		RR BUMPER CLIP	Replaced	0	3.6	No		25			16.2	Reviewing
<input type="checkbox"/>		0	2		RR BUMPER SIDE TOP COVER	Replaced	0	93.2	No		25			139.8	Reviewing
<input type="checkbox"/>		0	2		RR BUMPER SIDE SUPPORT R/L	Replaced	0	23.4	No		25			35.1	Reviewing
<input type="checkbox"/>		0	4		RR BUMPER LOWER BRACKET	Replaced	0	26	No		25			78	Reviewing
<input type="checkbox"/>		0	1		RR BUMPER STEP BRACKET	Replaced	0	282.1	No		25			211.58	Reviewing
<input type="checkbox"/>		0	1		RR END PANEL OUTER	Replaced	0	342.8	No		25			257.1	Reviewing
<input type="checkbox"/>		0	1		RR END PANEL INNER	Replaced	0	1104.7	No		25			828.53	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		RR END PANEL TOP SCUFF PLATE	Replaced	0	105.8	No		25			79.35	Reviewing
<input type="checkbox"/>		0	1		RR SPARE TYRE CARRIER	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RR BODY PANEL LH	Replaced	0	1546.9	No		25			1160.18	Reviewing
<input type="checkbox"/>		0	1		RR BODY PANEL AIR VENT LH	Replaced	0	62.7	No		25			47.03	Reviewing
<input type="checkbox"/>		0	1		RR TAILLAMP PANEL LH	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RR BODY PANEL INNER LH	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RR FLOOR CARPET	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RR FLOOR BOARD	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RR FLOOR PANEL (NPA)	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RR BODY PANEL INNER LH (NPA)	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		RR BODY PANEL RH (NPA)	Repair	0	0	No		25			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		RR TAILLAMP PANEL RH (NPA)	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	2		RR CHASSIS MEMBER R/L (NPA)	Repair	0	0	No		25			0	Deny






Labour






Add

Approve

Deny

Submit All
















	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK REAR ELECTRICAL WIRING SYSTEM	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		TO INSTALL REAR WINDSCREEN TO NEW TAILGATE	0	120	0	0	Reviewing	
<input type="checkbox"/>		0		TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REINSTALL BOTH REAR BODY PANEL GLASSES FOR NECESSARY REPAIRS	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, FLOOR BOARD, ETC. FOR NECESSARY REPAIRS. (INCLUDE REMOVE CARPET)	0	80	0	0	Reviewing	

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO REMOVE AND REINSTALL EXHAUST SILENCER FOR NECESSARY REPAIRS	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	0	1200	0	0	Reviewing	
<input type="checkbox"/>		0		TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	0	900	0	0	Reviewing	
<input type="checkbox"/>		0		TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	0	90	0	0	Reviewing	



Summary

Submit All

	 EDIT	0 SR NO	RR NO. PLATE NAME	Deny ACTION	ESTIMATED AMOUNT	0 ADJUSTED AMOUNT	SERVICEABLE COMMENT	 REMOVE
<input type="checkbox"/>		0	TAILGATE STICKER (70KM/H)	Reviewing		10	REPLACED	
<input type="checkbox"/>		0	TAILGATE STICKER (8PAX)	Reviewing		10	REPLACED	
<input type="checkbox"/>		0	REVERSE SENSOR	Reviewing		200	REPLACED	
<input type="checkbox"/>		0	RHR SEAT BOX (CUSTOMIZED)	Deny		0	SERVICEABLE	
<input type="checkbox"/>		0	RR BODY PANEL SEALANT LH	Reviewing		40	REPLACED	
<input type="checkbox"/>		0	RR END PANEL SEALANT	Reviewing		40	REPLACED	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$9,787.33	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$6,777.33			
Labour		\$0.00		\$2,590.00			
Miscellaneous		\$0.00		\$420.00			

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	7800		

Submit for Review