

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2102-029

DATE : 2-Feb-2021

POLICY NO. : MT/00608451/01

VEHICLE REG. NO. : SLN3398S

VEHICLE MAKE : CHEVROLET / ORLANDO 1.4AT

TO Motor Claim Department
India International Insurance Pte Ltd
 64 Cecil Street, #04-#05 IOB Building
 Singapore 049711
 Tel: 6347 6100 Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Rear Bumper	1	\$ 1,100.00	\$ 1,100.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 20.00	\$ 20.00
4	Rear Bumper Retainer LH	1	\$ 20.00	\$ 20.00
5	Rear Bumper Reflector LH	1	\$ 40.00	\$ 40.00
6	Rear Reinforcement	1	\$ 700.00	\$ 700.00
7	Rear Bumper Lower	1	\$ 450.00	\$ 450.00
8	Rear Stop/Reverse Lamp	1	\$ 180.00	\$ 180.00
Total Spare Parts				\$ 2,560.00
<u>SPECIAL NETT</u>				
9	Rear Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 200.00
<u>LABOUR</u>				
10	Spray painting (Rear Whole Bumper)	1	\$ 300.00	\$ 300.00
11	Repair and Refit Accident Affected Areas	1	\$ 400.00	\$ 400.00
12	Remove and Refit Rear Reverse Sensor	1	\$ 100.00	\$ 100.00
13	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00
Total Labour				\$ 850.00
Amount Before Excess				\$ 3,610.00
Add GST @ 7%				252.70
Total Amount Payable				\$ 3,862.70

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.