Automotive Repair Centre Pte Ltd CO. Reg. No.: 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO.: EST2102-029

DATE: 2-Feb-2021

POLICY NO.: MT/00608451/01

VEHICLE REG. NO. : SLN3398S

VEHICLE MAKE: CHEVROLET / ORLANDO 1.4AT

Motor Claim Department

India International Insurance Pte Ltd

64 Cecil Street, #04-#05 IOB Building

Singapore 049711

Tel: 6347 6100 Fax: 6224 4174 / 6225 7743

FOF	FOR SURVEYOR								
1									

ESTIMATE REPAIR COST

NO.	DESCRIPTION DESCRIPTION		6.	Milia Joseph			
	SPARE PARTS	QUANTIT	TY I	JNIT COST		TOTAL COST	
1	Rear Bumper / per	-					
2	Daniel D	1	.\$	1,100.0	0 \$	1,100.00	
3	Pear Pump and David	10	\$	5.00	5	50.00	
4	Poor Poor	1	\$	20.00	\$	20.00	
5	/: 010	1	\$	20.00	\$	20.00	
6	Poor Paint	1	\$	40.00	\$	40.00	
7	Pear Ruman I	1	\$	700.00	S	700.00	
8	/\ck.	1	\$	450.00	5	450.00	
0	Rear Stop/Reverse Lamp	1	\$	180.00	S	180.00	
	CDECU		Tota	Spare Parts	-		
_	SPECIAL NETT			· · · · · · · · · · · · · · · · · · ·	-	2,560.00	
9	Rear Reverse Sensor / Short	1	5	200.00	-		
				200.00	\$.	200.00	
	LABOUR		lotal	Special Nett	\$	200.00	
0	Spray painting (Rear Whole Bumper)	1					
1	Repair and Refit Accident Affected Areas	1	\$	300.00	\$	300.00	
2	Remove and Refit Rear Reverse Sensor		\$	400.00	\$	400.00 3	
3	Check and Rectify Electrical Wiring	1	\$	100.00	\$	100.00 3	
mate	Prepared by: Oscar Pong	1	\$	50.00	\$	50.00 3	
abov	e is an estimate based on a surface to the state of the s		Tot	al Labour	\$	850.00 6	
asiona	ally, worn or damaged parts are discovered after work has been started.	Amo	ount Bef	ore Excess	\$	3,610.00	
he fir	st inspection. Because of this, the above price are not guaranteed			GST @ 7%		252.70	

252.70 Total Amount Payable \$ 3,862.70

Repair day - 3 days.

After puin photo

Signature:

Acknowledged by Repairer

is subject to final approval from Insurance Company

• Supplementary item(s) must be resurveyed and • No illegal modification(s) is allowed

• Third party survey is on a "Without Prejudice" basis

· Parts prices are subject to confirmation

To display damaged part(s) during resurvey

 To resurvey before/after spray painting the Repairer of the following: **LKK Auto Consultants** hence notify

Jun Pin (441) 18/02/2021 TP withy prejudice.

Page 1 of 1

Supplementary Estimate

38 Woodlands Industrial Park E1 #05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotive repair centre.com.sg

Quotation on parts and labour are current and subject to change.

ESTIMATE NO. : EST2102-029 (SUP)

DATE: 15-Feb-2021

POLICY NO.: AUTO&GEN P10175646R01

VEHICLE REG. NO. : SLN3398S

VEHICLE MAKE: CHEVROLET / ORLANDO 1.4AT

Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building
Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

ESTIMATE REPAIR COST

		-				
NO.	DESCRIPTION	QUANTITY	UNIT COST		TOTAL COST	
	SPARE PARTS					
1	Rear Tow Eye Cover / CRY	1	\$	20.00	\$	20.00
2	Rear Bumper Lower (Gray) /SCR	1	\$	300.00	\$	300.00
Total Spare Parts				\$	320.00	
	SPECIAL NETT					
	Total Special Nett				\$	-
	<u>LABOUR</u>					
Estimate prepared by: Raymond Tan The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident.			To	tal Labour	\$	-
		Amount Before Excess Add GST @ 7%			\$	320.00
						22.40
		on T o	n Total Amount Payable			342.40
the firs	t inspection. Because of this, the above price are not guaranteed.					

Please arrange this vehicle to be surveyed soonest possible. Thank you.

2,191.50 288 200 660 3,339.50 2,611.60

2/5 2,650 3 dlays