

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

29/01/2021

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP AIG.
Jasper.

Accident date: 04/01/2021

Estimated repair cost for vehicle no: SMG4877U SUBARU FORESTER 2.0I-L CVT '18

CHASSIS: JF1SJ5KC5JG112661

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented</i>		\$1,192.30	✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$55.00	\$110.00	+
3	2	Rear Boot Lid Shock Absorber <i>new</i>	\$154.00	\$308.00	+
4	1	Rear Boot Lid Emblem Logo		\$65.00	✓
5	1	Rear Boot Lid Subaru Logo		\$68.00	✓
6	1	Rear Boot Lid Forester Logo		\$68.00	✓
7	1	Rear Boot Lid AWD Logo		\$65.00	✓
8	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00	+
9	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$560.30	264
10	1	Rear Boot Lid Weatherstrip <i>new</i>		\$160.30	+
11	1	Rear Boot Lid Inner Trim Board <i>3pc</i>		\$220.30	+
12	10	Rear Boot Lid Inner Trim Board Clip <i>3pc</i>	\$6.50	\$65.00	+
13	1	Rear Boot Lid Windscreen Seal <i>3pc</i>		\$85.00	✓
14	2	Rear Boot Lid Windscreen Side Seal	\$75.00	\$150.00	✓
15	1	Rear Boot Lid Reverse Camera <i>new</i>		\$850.00	+
20	1	Rear Bumper <i>Damaged</i>		\$980.30	600.30
21	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00	30
22	2	Rear Bumper Side Retainer <i>new</i>	\$38.00	\$76.00	✓
23	1	Rear Bumper Side Reflector <i>3MP</i>		\$42.00	X
24	1	Rear Bumper Towing Cover <i>3pc</i>		\$22.00	+
26	1	Rear Bumper Reinforcement <i>Bent</i>		\$320.80	✓
27	2	Rear Bumper Reinforcement Bracket <i>Not new</i>	\$28.60	\$57.20	X
28	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$380.00	200/sw
30	2	Rear Fender Inner Trim Board <i>3pc</i>	\$486.30	\$972.60	+
31	8	Rear Fender Inner Trim Board Clip <i>3pc</i>	\$6.50	\$52.00	+
32	1	Rear End Panel <i>Dented</i>		\$332.00	✓
33	1	Rear End Panel Top Garnish <i>Damaged</i>		\$90.00	✓
34	1	Rear Spare Tyre Panel <i>new</i>		\$632.40	+
35	1	Rear Spare Tyre Panel Top Cover <i>new</i>		\$336.00	+

36	1	Rear Spare Tyre Panel & End Panel Sealant		\$450.00	+
37	2	Rear Spare Tyre Panel Side Foam Tool Box	\$85.50	\$171.00	+
38	1	Rear Spare Tyre Panel Foam Tool Box		\$161.20	+
39	1	Rear Centre Exhaust		\$1,048.40	+

3406.40
2725.12

S.N: 2w

Subtotal :- \$10,206.10

Labour charges

To remove & refit cushion & trim board	\$280.00 80
To remove & refit reverse sensor	\$100.00 60
To remove & refit reverse camera	\$180.00 60
To remove & refit rear windscreen	\$150.00 120
To remove & refit rear exhaust	2290 \$200.00 X
Ceramic Coating	\$800.00 X
Gum	\$60.00 /
To check wiring	\$100.00 30
Tuff kote	\$150.00 80
Panel beating	\$2,400.00 800
Spray painting	\$2,000.00 1000

Subtotal :- \$6,420.00

Total :- \$16,626.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Supplementary 1: 900
Supplementary 2: 380
total: 6495.12
h/s: 52k
06 Days.
52k

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

29/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 04/01/2021

Supplementary repair cost for vehicle no: SMG4877U SUBARU FORESTER 2.0I-L CVT '18

CHASSIS: JF1SJ5KC5JG112661

S/n	Qty	Items	U/price	Amount
1	1	Rear Bumper Lower Spoiler <i>Rehnd</i>		\$1,800.00 800(S/N)

Subtotal :- \$1,800.00

Labour charges

To remove & refit body kit

~~\$200.00~~ 100.

Subtotal :- \$200.00

Total:- \$2,000.00

Supplementary : 800

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

01/03/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 04/01/2021

Supplementary repair cost for vehicle no: SMG4877U SUBARU FORESTER 2.0I-L CVT '18

CHASSIS: JF1SJ5KC5JG112661

S/n	Qty	Items	U/price	Amount
1	1	Rear Bumper Top FORESTER Chrome <i>deduct</i>		\$680.00 <i>380/sn</i>

Subtotal :- \$680.00

Supplementary 2: 380.