

MCS Garage

TP Budget Direct.
Denise.

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 / 6538 4322

6871090036

Vehicle number: SMM9964L

Vehicle Made & Model: HONDA FREED

Qty	List Items	Amount \$	
1	Tailgate <i>Distorted.</i>	1,690.60	1285
1 set	Tailgate glass moulding <i>new</i>	132.20	✓
1	Tailgate emblem "H"	48.80	✓
1	Tailgate emblem "FREED" <i>new</i>	68.60	✓
1	Tailgate emblem "HYBRID" <i>new</i>	82.60	✓
1	Tailgate emblem "HYBRID"	783.20	X
2	Tailgate lamps - L/R @ 391.60 <i>new</i>	281.90	X
1	Tailgate chrome moulding	280.30	✓
1	Tailgate inner lock <i>Damaged</i>	481.30	345
1	Tailgate inner trim board <i>new</i>	155.60	✓
1	Tailgate w/strip <i>at</i>	362.40	X
2	Tailgate dampers - L/R @ 181.20 <i>new</i>	131.00	X
2	Tailgate hinges @ 65.50	24.40	X
2	Tailgate stoppers @ 12.20	963.20	X
2	Taillamps - L/R @ 481.60 <i>new</i>	281.60	+
1	Taillamp filler panel - LH <i>Repair</i>	1,260.30	885
1	Rear bumper <i>Distorted</i>	179.80	X
2	Rear bumper reflectors - L/R @ 89.90 <i>new</i>	117.20	✓
2	Rear bumper side retainers - L/R @ 58.60 <i>new</i>	241.20	X
1	Rear bumper undercover <i>new</i>	680.60	✓
1	Rear end panel <i>Dented</i>	691.90	X
1	Rear end panel inner member <i>Repair</i>	281.90	✓
1	Rear end panel top garnish <i>Dented</i>	631.50	X
1	Rear floor mat <i>new</i>	1,260.60	X
1	Rear floor panel <i>Repair</i>	1,363.20	476
2	Rear fender inner trim boards @ 681.60 <i>new</i>	671.60	X
1	Rear exhaust silencer <i>new</i>		
Sub-total		13,147.50	
Less 20%		2,629.50	
Total List		10,518.00	

Vehicle number: SMM9964L

Vehicle Made & Model: HONDA FREED

Special Nett Items

1 set	Tailgate glass sealant	new	80.00	60
1 set	Rear no. plate	new	60.00	X
1	Rear bumper chrome plate	But	450.00	200.
1 set	Rear bumper clip	new	35.00	✓
1 set	Rear reverse sensor	new	280.00	new
1	Rear reverse camera	new	450.00	X.
			<u>1,355.00</u>	

495

Labour charges

To check rear electrical wiring	50.00	30
To remove, refix rear tailgate glass	180.00	120
To remove, refix rear reverse sensor / camera	120.00	100
To remove, refix rear exhaust systems	100.00	X
To remove, refix rear interior trims to assist repair	180.00	60
Transfer & reinstall tailgate components to new tailgate	150.00	80
To respray undercoating	150.00	60
To respray painting and etc	1,200.00	800
Panel beating, cut, weld remove & replacing above parts	1,500.00	1000.
Total Labour	<u>3,630.00</u>	

2250

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 15,503.00

Total: 6616.04

H/S: 5.2K. ✓

06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: