



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                 |                            |  |
|--|--|-----------------|----------------------------|--|
| SOMPO INSURANCE SINGAPORE PL<br>50 RAFFLES PLACE #03-03<br>SINGAPORE LAND TOWERSINGAPORE 048623  |  |                 | Ref: CS/SMO21001600/Uqf3e2 |  |
|  |  |                 | Date: 15/03/2021           |  |
|  |  |                 | Code: SMO                  |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                 |                            |  |
| Insured Veh.   | GBK 4571K  | Veh. Inspected  | SMU 7577S                  |  |
| Policy No.   | D20MTHCVE001916  | Coverage (\$)   | 0.00                       |  |
| Claim No.  | CMTD2100334/MYE  | Excess (\$)     | 0.00                       |  |
| Assign From  | GRACE TEO  | Assign Date     | 02/02/2021                 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                 |                            |  |
| Make & Model   | B.M.W. 216D (A)  | c.c             | 1496                       |  |
| Engine No.   | HIDDEN   | Year of Reg.    | 2016                       |  |
| Chassis No.  | WBA2E320005B45180  | Colour          | BLACK                      |  |
| Odometer   | 62252 KM   | Steering        | IN ORDER                   |  |
| Brakes   | IN ORDER   | Modification    | SPORTS RIM                 |  |
| General  | GOOD   |                 |                            |  |
| <b>3. Conditions of Tyres</b>  |  |                 |                            |  |
|  | Size   | Make            | Balance                    |  |
| R/H Front Tyre   | 225/45 R18   | BRIDGESTONE     | 7 mm                       |  |
| L/H Front Tyre   | 225/45 R18   | BRIDGESTONE     | 7 mm                       |  |
| R/H Rear Tyre  | 225/45 R18   | GOODYEAR        | 7 mm                       |  |
| L/H Rear Tyre  | 225/45 R18   | GOODYEAR        | 7 mm                       |  |
| <b>4. Description of Damages</b>   |  |                 |                            |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |  |                 |                            |  |
| <b>5. General Information</b>  |  |                 |                            |  |
| Accident Date  | 27/01/2021   | Inspection Date | 03/02/2021                 |  |
| Survey held at   | BIFROST AUTO PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#01-49 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                 |                            |  |
| <b>5a. Remarks</b>   |  |                 |                            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                            |  |
| <b>5b. Estimate Days of Repair</b>   |  |                 |                            |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  |                 | 3 Working Days             |  |