

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SM021001600/U9f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMU 75775
B. Frost

at Workshop m/s

of

Insured:

GBK 4571K

Policy No.

Claims No.

CNTP2100334/NOYE

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

£78k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3
20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

27047813

Vehicle: IN / OUT

Date:

Person Contacted:

Rep 12k

Date / Time

Action / Instruction

CWY 12/2/21

24/1/21 2/5 £2000 confirmed with idhwen (Red 502884, 72%)
01/3/21 @ 10.43am revised to Melvin Ye by email.

Veh No:

SMU 75775

Yr Regn:

20/9/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

BMW 216D

c.c 1496

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

62252

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA2E320005B45180

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R18

R:

BY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

27/1/21

D.O.I.

3/2/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) 01/3/21

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format :

7P

Lump Sum / I.B.I. (\$

2000

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

: Submit to insurance

Not Authorized
1/3 & 2000/
3 days.
The other repair

Bitrost Auto Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49, S1415875
Tel: 65 64524457 / Fax: +65 64524558
Co. Reg No.: 201929175W

Estimate for SMU7577S(BMW 216i)

1 *BOOTLID	R	\$1,504.35	X
1 *BOOTLID EMBLEM	nee	\$85.65	—
1 *RR BUMPER LH SIDE GUIDE	11	\$161.35	X
1 *RR BUMPER RH SIDE GUIDE	11	\$161.35	X
1 *REAR BUMPER Top chrome	one 350	\$658.10	✓
1 *RR BUMPER RH INNER SIDE GUIDE	11	\$67.55	X
1 *RR BUMPER LH INNER SIDE GUIDE	11	\$67.55	X
1 *REAR BUMPER TRIM STRIP (CHROME)	12mm Bent	\$108.40	—
1 *REAR BUMPER PANEL PRIMED	DD 1045.45	\$1,245.45	—
1 *ULTRASONIC SENSOR BLACK	1/5 shield 209.32	\$248.70	✓
4 *SET MOUNTS PDC SENSOR REAR	11	\$62.95	X
4 *DECOUPING RING PDC TORQUE CONVERTER	11	\$120.80	X
1 *(DG) CLEANER R1 (100ML)	11	\$26.15	X
1 *(DG/SL) W/SCREEN SEALANT	11	\$263.10	X
1 *(DG/SL) GLASS PRIMER 30ML (VP206)	11	\$27.85	X
		\$4,809.30	
Less 5%		\$240.47	
		\$4,568.84	

REPLACING REAR BUMPER PANEL AND ATTACHMENTS, BOOTLID	\$800.00	380
SPRAY REAR DAMAGED PORTION	\$800.00	400
TO REPLACE REAR WINDSCREEN GLASS	11 \$180.00	X
TO CONDUCT WATER LEAK TESTS	11 \$80.00	X
TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	11 \$400.00	X
TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	100.00	50
TO CARRY OUT BODY CAVITY PRESERVATION	11 \$100.00	X
	\$2,460.00	
TOTAL	\$7,028.84	

p-179882
52
p-170887
1-830
283887
202
2031

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: