

Date: 02.02.2021
Vehicle No: SMN440K
Model: TOYOTA VOXY HYBRID 1.8X
Chassis: ZWR800386459-2019
Reg. Year: 2019

Third Party Insurer: AGI
Third Party Veh No: SMF9897J
Date of Accident: 30.01.2021

81443.67
81445.67

Not Authorised
Reamy Bypain
3 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	Brc/Cut	\$1,393.20
2	FRONT BUMPER SIDE BRACKET LH	1	CW	\$75.30
3	FRONT BUMPER REINFORCEMENT	1		\$419.70
4	FRONT BUMPER ABSORBER FOAM	1		\$125.20
5	FRONT FENDER LH	1		\$850.30
6	FRONT FENDER INNER LINER LH	1		\$188.60
SUB TOTAL				\$3,052.30
LESS 25%				-\$763.08
PARTS TOTAL				\$2,289.23

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		\$50.00
2	FRONT FENDER INNER LINER CLIPS LH	1		\$40.00
S/N TOTAL				\$90.00

OUR CHARGES:

OUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS
ETC.

2001
\$500.00

OUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT
FRONT BUMPER, FRONT FENDER LH & ETC.

4001
\$500.00

CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$100.00 101

LABOUR TOTAL \$1,100.00

TOTAL \$3,479.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date: Branch

Head office

5 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1003

Branch (Motor Insurance Claims)

8A 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

