

ASSIGNMENT

From

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKD7013R

Yr Regn:

2011 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A6

C.C

1984

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

1627/89

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAK 222469CN/067063

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55 R17

R:

225/55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

02/02/21

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG

Pending DV / Final Bill

MV: 38K

PV: 28.3K

Nett: 9.7K

Part by part \$3857.22 @ 3days
(Red: 4393.72, 53%)

Date/Time, File Pass to?



: Preli. Report



: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee

Transportation

S + PS

Photos

Other

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

2)

Date/Time, File Return to?

44 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.HAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0079/2021/GW
DATE	:	25/01/2021
WIP	:	12750

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SLW 5020 X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR MASAGOS ZULKIFLI BIN MASAGOS MOHAMAD
ADDRESS	:	7A DUNBAR WALK SINGAPORE 459280
TELEPHONE	:	HP +65 97883445
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2100284233-09
VEHICLE NO	:	SKD 7013 R
MODEL CODE	:	AUDI A6 2.0 TFSI MU
MODEL YEAR	:	29/12/2011
ENGINE NO	:	CDN235119
CHASSIS NO	:	WAUZZZ4G9CN067063
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	22/01/2021
PLACE OF ACCIDENT	:	OFF RAMP ROCHOR ROAD

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKD 7013 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND KICK SENSOR . CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	 
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	 500 
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00	550 
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	 
TOTAL LABOUR CHARGES		: \$ 2,752.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKD 7013 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 REAR BUMPER <i>del d</i>		\$ 2,832.00 ✓	2265.60
2 REAR BUMPER FIXING PARTS <i>nee</i>		\$ 276.00 +	
3 REAR BUMPER SPOILER <i>nee</i>		\$ 347.00 +	
4 REAR BUMPER SECURING STRIP ? X <i>nn</i>		\$ 172.00 ?	
5 REAR BUMPER REINFORCEMENT BEAM <i>nee</i>		\$ 1,012.00 +	
6 REAR BUMPER REINFORCEMENT BEAM SEAL-LH/RH <i>nee</i>	2	\$ 28.00 +	
7 REAR BUMPER GUIDE SECTION-LH/RH <i>nee</i>	2	\$ 66.00 +	
8 REAR BUMPER CONNECTING PIECE-LH/RH <i>nee</i>	2	\$ 25.00 +	
9 REAR BUMPER GUIDE PROFILE-LH/RH UPPER <i>nee</i>	2	\$ 116.00 +	
10 REAR BUMPER GUIDE SECTION-CENTER <i>nee</i>		\$ 106.00 +	
11 REAR SENSOR <i>nee</i>	2	TBC +	
12 REAR SENSOR SEAL RING <i>nee</i>	4	\$ 6.00 +	
13 REAR LID WEATHERSTRIP <i>nee</i>		\$ 205.00 +	
14 REAR TRIM FOR CROSS PANEL <i>nee</i>		\$ 133.00 +	
15 SUNDRIES ?		\$ <i>nee</i> 200.00 ?	9.60
TOTAL SPARE PARTS	:	\$ 5,524.00	
TOTAL LABOUR CHARGES	:	\$ 2,752.00	
GRAND TOTAL	:	\$ 8,276.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian L
02/02/21

Not Authorized, 03 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT