

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____
 To inspect Vehicle No. _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 2100 284233
 Claims No. 665759550684
 Sum Insured: _____ Excess: #01-
 (Client's Record)
 Make of Veh: _____

Veh No: SKD7013R Yr Regn: 2011, Dec
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi A6 c.c. 1984
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 162789 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAK722469CN067063
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : **Yes** or No
 GIA / PR Seen: _____ Consistent? : **Yes** or No
 Est. Repairs: _____ days Res.: **Yes** or No
 Lum Sum: _____ % 3 Val.: **Yes** or No
 CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**

Tyre Size: F: 225/55 R17
 R: 225/55 R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front 06 mm / Rear 06 mm
 R/Bal. 06 mm / L/Bal. 06 mm
 D.O.A. _____ D.O.I. 02/02/21
 Survey held at Premier
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD AIG</u> Pending DV / Final Bill
	<u>Part by part \$3857.28 @ 3days</u> <u>(Red: 4398.72, 53%)</u>
	<u>MV: 38K.</u>
	<u>PV: 28.3K.</u>
	<u>Nett: 9.7K</u>

Date/Time, File Pass to? : **Preli. Report**
 : **Final Report**

1) _____ Date/Time, File Return to? _____

2) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Insp (\$ _____)
 : Travel and (\$ _____)

Survey Fee	_____
Transportation	_____
S + PS	_____
Photos	_____
Other	_____
TOTAL	_____

PREMIUM AUTOMOBILES



44 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.HAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0079/2021/GW
DATE : 25/01/2021
WIP : 12750

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SLW 5020 X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR MASAGOS ZULKIFLI BIN MASAGOS MOHAMAD
ADDRESS : 7A DUNBAR WALK
SINGAPORE 459280
TELEPHONE : HP +65 97883445
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100284233-09
VEHICLE NO : **SKD 7013 R**
MODEL CODE : AUDI A6 2.0 TFSI MU
MODEL YEAR : 29/12/2011
ENGINE NO : CDN235119
CHASSIS NO : WAUZZZ4G9CN067063
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22/01/2021
PLACE OF ACCIDENT : OFF RAMP ROCHOR ROAD

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKD 7013 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND KICK SENSOR . CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500 ✓
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00	550 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,752.00</u>	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKD 7013 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 REAR BUMPER <i>del</i>		\$ 2,832.00 ✓	✓ 2265.60
2 REAR BUMPER FIXING PARTS <i>nee</i>		\$ 276.00 +	
3 REAR BUMPER SPOILER <i>nee</i>		\$ 347.00 +	
4 REAR BUMPER SECURING STRIP ?		\$ 172.00 ?	
5 REAR BUMPER REINFORCEMENT BEAM <i>nee</i>		\$ 1,012.00 +	
6 REAR BUMPER REINFORCEMENT BEAM SEAL-LH/RH <i>nee</i>	2	\$ 28.00 +	
7 REAR BUMPER GUIDE SECTION-LH/RH <i>nee</i>	2	\$ 66.00 +	
8 REAR BUMPER CONNECTING PIECE-LH/RH <i>nee</i>	2	\$ 25.00 +	
9 REAR BUMPER GUIDE PROFILE-LH/RH UPPER <i>nee</i>	2	\$ 116.00 +	
10 REAR BUMPER GUIDE SECTION-CENTER <i>nee</i>		\$ 106.00 +	
11 REAR SENSOR <i>nee</i>	2	TBC +	
12 REAR SENSOR SEAL RING <i>nee</i>	4	\$ 6.00 +	
13 REAR LID WEATHERSTRIP <i>nee</i>		\$ 205.00 +	
14 REAR TRIM FOR CROSS PANEL <i>nee</i>		\$ 133.00 +	
15 SUNDRIES ?		\$ <i>nee</i> 200.00 ?	9.67
TOTAL SPARE PARTS	:	\$ 5,524.00	
TOTAL LABOUR CHARGES	:	\$ 2,752.00	
GRAND TOTAL	:	\$ 8,276.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *02/02/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *we Authorized , 03 days*

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT