

L/Ce

NTUC

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.02.2021

REPAIR ESTIMATE

Time: 16:09:20

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305451354
 REGN NO : SHC8815C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 04.03.2016
 DATE/TIME IN : 30.01.2021 14:45
 ACCIDENT DATE : 30.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1 L	1,106.00	20.00	884.80	/ Re
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ m/c
0003	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1 L	228.00	20.00	182.40	/ At
0004	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1 L	119.50	20.00	95.60	/ Re
0005	04-01-0103-0740-G	BEAM-RR BUMPER#	1 L	428.40	20.00	342.72	?
0006	04-01-0103-0742-G	STAY-RR BUMPER LH	1 L	160.60	20.00	128.48	?
0007	04-01-0103-0743-G	STAY-RR BUMPER RH	1 L	160.60	20.00	128.48	?
0008	04-01-0103-0907-G	BRKT ASSY-RR BUMPER SIDE	1 L	35.60	20.00	28.48	/ Re
0009	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1.000 N	135.70	10.00	122.13	/ Am
0010	04-01-0103-0851-G	REFLECTOR/REFLEX ASSY-RR	1 L	32.00	20.00	25.60	/ At
0011	04-01-0103-0852-G	REFLECTOR/REFLEX ASSY-RR	1 L	32.00	20.00	25.60	?
0012	04-01-0103-0696-G	PANEL ASSY-BACK #	1 L	526.70	20.00	421.36	/ BT
0013	04-01-0103-0710-G	EXTENSION ASSY-QTR OTR RR	1 L	225.60	20.00	180.48	?

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.02.2021

Time: 16:09:20

REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305451354
 REGN NO : SHC8815C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 04.03.2016
 DATE/TIME IN : 30.01.2021 14:4
 ACCIDENT DATE : 30.01.2021

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT					
0014	04-01-0103-0711-G EXTENSION ASSY-QTR OTR RR	1	L	225.60	20.00	180.48	?
0015	04-01-0103-2159-G MEMBER ASSY-RR FLOOR END	1	L	495.50	20.00	396.40	X repair
0016	04-01-0103-0576-G PANEL ASSY-QUARTER OTR LH	1	L	2,201.10	20.00	1,760.88	/ Buc
0017	04-01-0103-1053-G TRIM-TRANSVERSE RR	1	L	57.70	20.00	46.16	/ de
0018	04-01-0103-0577-G PANEL ASSY-TRUNK LID#	1	L	2,174.90	20.00	1,739.92	/ Buc
0019	04-01-0103-0721-G LATCH ASSY-TRUNK LID	1	L	114.90	20.00	91.92	/ DT
0020	04-01-0103-0712-G HINGE ASSY-TRUNK LID LH	1	L	142.30	20.00	113.84	/ 4BT
0021	04-01-0103-0713-G HINGE ASSY-TRUNK LID RH	1	L	142.30	20.00	113.84	/ 4BT
0022	04-01-0103-0786-G EMBLEM-CRDI	1	L	52.40	20.00	41.92	/
0023	04-01-0103-0787-G EMBLEM-I40	1	L	67.90	20.00	54.32	/
0024	04-01-0103-0800-G SYMBOL MARK-TRUNK LID	1	L	63.10	20.00	50.48	/
0025	28-01-0103-0005-A REAR BOOT LOGO CTPL	1	N	30.00	10.00	27.00	/

REPAIR ESTIMATE

Page: 3

JOB NO : 305451354
REGN NO : SHC8815C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 04.03.2016
DATE/TIME IN : 30.01.2021 14:4
ACCIDENT DATE : 30.01.2021

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT					
0026	28-01-0103-0006-A REAR BOOT TEL NUMBER CTPL	1	N	30.00	10.00	27.00	/
0027	05-01-0199-0032-A WINDSCREEN AHESIVE-310MLC	2	N	46.00	10.00	41.40	/ {acc
0028	04-01-0103-0745-G MOULDING-RR WDO GLASS LWR	1	L	51.80	20.00	41.44	/
0029	04-01-0103-0581-A LAMP ASSY-RR COMB O/S LH#	1	L	697.80	20.00	558.24	/ CFA .
0030	04-01-0103-0584-G LAMP ASSY-RR COMB I/S LH(	1	L	1,131.20	20.00	904.96	/ Cut .
0031	04-01-0103-0585-A LAMP ASSY-RR COMB O/S RH#	1	L	697.80	20.00	558.24	/ Cut .
0032	04-01-0103-0583-G LAMP ASSY-RR COMB I/S RH(	1	L	1,131.20	20.00	904.96	/
SUB-TOTAL						10,237.13	


JOB NATURE

0000 L PANEL BEATING

0001 23-502 SPRAY PAINTS AND AFFECTED AREA

1680.00

1250.00



COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.02.2021

Time: 16:09:20

Page: 4

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305451354
REGN NO : SHC8815C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 04.03.2016
DATE/TIME IN : 30.01.2021 14:4
ACCIDENT DATE : 30.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 17-01	CHECK ALL LIGHTING	50.00	20 30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	/
0004 20-20	REMOVE/REFIX RR W/SCREEN TO ASST R/P	120.00	/
0005 20-22	REMOVE/REFIX REVERSE SENSOR	120.00	40
0006 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	200.00	60
		SUB-TOTAL	: 3,470.00

TOTAL : 13,707.13

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

8 Days.
w/psm repair
After repair photos
Gue Riap
01/2/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: