

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-44
Premier @ Kaki Bukit (Gate 1)
Singapore 415875
Tel: 63441918

Date : 01/02/2021
Vehicle : SLV5069L
Make/Model : Toyota C-HR Hybrid 1.8
ORD : 2017
Chassis : ZYX102085469
ODO : 109024
ACC Date : 30/01/2021

China Taiping Insurance (S) Pte Ltd

3 Anson Road, #15-00 Springleaf Tower,
Singapore 079909

Estimate

S/N	Qty	Description & Specification	Amount S\$	
		<u>List Items</u>		
1	1	Rear door RH	1284.90	\$1,384.50 <i>btv</i>
2	1	Rear door outer garnish RH		\$251.80 <i>cut</i>
3	1	Rear door w/stripe RH		\$201.80 <i>X un</i>
4	1	Rear door quarter glass RH		\$374.20 <i>X un</i>
5	1	Rear door quarter glass moulding RH		\$99.90 <i>X un</i>
6	1	Rear door protector RH	322.50	\$465.80 <i>cut</i>
7	1	Rocker panel garnish RH	546.70	\$614.90 <i>cut</i>
8	1	Rear sport rim RH		\$688.50 <i>cut</i>
9	1	Rear fender RH		\$818.20 <i>btv</i>
10	1	Rear fender arch garnish RH	330.40	\$474.40 <i>cut</i>
11	1	Rear fender inner shield RH		\$168.50 <i>cut</i>
12	1	Rear fender inner air duct RH		\$122.60 <i>de</i>
13	1	Rear bumper top		\$989.70 <i>de</i>
14	1	Rear bumper bottom	580	\$766.30 <i>de</i>
15	1	Rear bumper side retainer RH		\$111.80 <i>de</i>
16	1	Rear bumper reflector RH		\$92.70 <i>cut</i>
17	1	Rear bumper reflector garnish RH		\$200.30 <i>cut</i>
18	1	Rear bumper sensor outer RH	NW ✓ \$200	\$256.90 <i>XXXX</i>
19	1	Rear bumper sensor outer ring RH		\$50.80 <i>rec</i>
20	3	Rear bumper sensor ring / holder		\$152.40 <i>rec</i>
21	1	Rear bumper lower cover RH		\$155.60 <i>de</i>
22	1	Rear bumper bracket RH		\$98.80 <i>X un</i>
23	1	Rear end panel	7067.40	\$497.50 <i>RD</i>
			5300.55	
				Less 25%
				\$2,259.48
				List Total
				\$6,778.42
		<u>S/Nett Items</u>		
1	1set	Rear door inner trim board clips RH		\$80.00 <i>X un</i>
2	1set	Rear door protector clips RH		\$40.00 <i>X un</i>
3	1set	Rocker panel garnish clips RH		\$60.00 <i>10 rec</i>
4	1set	Rear fender arch garnish clips RH		\$40.00 <i>10 rec</i>
5	1set	Rear fender inner shield clips RH		\$40.00 <i>10 rec</i>
6	1set	Rear fender inner garnish clips RH		\$80.00 <i>X un</i>

7	1set	Rear bumper clips						\$100.00	30 net	
8	1set	Rear bumper lower cover clips						\$40.00	X 44	
9	1set	Rear door sealant RH						\$60.00	X 44	
10	1set	Rear fender sealant RH						\$60.00	30 net	
11	1set	Rear end panel sealant						\$60.00	X 44	
								S/Nett Total	\$660.00	
		Labour							90	
1		To cut, weld rear fender RH, rear end panel, to replace rear door RH, to repair and re-align on all accident affected areas							\$1,400.00	1000
2		To putty and respray on rear RH accident portion							\$1,200.00	1000
3		To check rear lighting and wiring							\$100.00	30
4		To apply anti-rust corrosion on rear RH affected areas							\$100.00	30
5		To transfer rear door RH mechanism to new door							\$100.00	60
6		To transfer rear RH new rim to old tyre							\$50.00	30
7		To do wheel balancing on rear RH new rim							\$50.00	30
8		To do computerised wheel alignment							\$100.00	80
9		To remove and refit rear upholstery, lining, garnish etc to assist repair							\$300.00	60
								Labour Total	\$3,400.00	
								Grand Total	\$10,838.42	
									2220	
Trident Auto Service Centre Pte Ltd										

Taufik 97495749
 'WP' 3/2/21 @ 1230pm
 L/s Resurvey after repair
 Taufik @ lkharto.com.
 07 days - 08 days

~~51510555~~ 5300.55
~~2222~~ 90
~~2222~~ 2320
~~2222~~ 7710.55
~~2222~~ L/\$6150
 8 DAYS
 Jollys.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by the insurance company
 is subject to final approval from insurance company

Acknowledged by Repairer
 Signature:
 Date: