

Kg

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP7136H

LAD2102-004

Not Authorized

Running B4paint

81822-78

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SMP 7136H
MR053REH604598945
TOYOTA
COROLLA ALTIS
31.1.2021
TOKIO MARINE
11/10/2019

PART	LIST
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ <i>R</i> 419.48 ✓
1 SEAL, REAR BUMPER SIDE, LH	\$ <i>Sn</i> 57.86
1 SEAL, REAR BUMPER SIDE, RH	\$ <i>Sn</i> 57.86
1 RETAINER, REAR BUMPER SIDE, LH	\$ <i>Sn</i> 114.77
1 RETAINER, REAR BUMPER SIDE, RH	\$ <i>Sn</i> 114.77
1 RETAINER, REAR BUMPER, UPPER LH	\$ <i>Sn</i> 63.42
1 RETAINER, REAR BUMPER, UPPER RH	\$ <i>Sn</i> 63.42
1 PAD, REAR BUMPER, CENTER	\$ <i>Sn</i> 6.62
1 PAD, REAR BUMPER	\$ <i>Sn</i> 15.96
1 BRACKET, REAR BUMPER SEAL, LH	\$ <i>Sn</i> 8.09
1 BRACKET, REAR BUMPER SEAL, RH	\$ <i>Sn</i> 8.09
1 ARM, REAR BUMPER, LH	\$ <i>R</i> 71.61
1 ARM, REAR BUMPER, RH	\$ <i>R</i> 71.61
1 PIECE, REAR BUMPER	\$ <i>Sn</i> 4.31
1 COVER, REAR BUMPER	\$ <i>Sn</i> 584.22 ✓
1 WEATHERSTRIP, LUGGAGE COMPARTMENT DOOR	\$ <i>Sn</i> 184.59 X
1 PANEL SUB-ASSY, LUGGAGE COMPARTMENT DOOR	\$ <i>R</i> 832.86 X
TOTAL	\$ 2,679.50
25%	\$ 669.87
	\$ 2,009.62

Special Nett

1SET PARKING AID	\$ <i>Od</i> 700.00 <i>220sn</i>
1SET REAR BUMPER CLIP	\$ <i>Sn</i> 66.00 <i>50sn</i>
1SET REAR LH SIDE BUMPER RETAINER CLIP	\$ <i>Sn</i> 35.00 X
1SET REAR RH SIDE BUMPER RETAINER CLIP	\$ <i>Sn</i> 35.00 X
1SET REAR RH UPPER BUMPER RETAINER CLIP	\$ <i>Sn</i> 35.00 X
1SET REAR LH UPPER BUMPER RETAINER CLIP	\$ <i>Sn</i> 35.00 X
1 REAR BUMPER REFLECTOR SCREW	\$ <i>Sn</i> 15.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP7136H

LAD2102-004

1822-78

2	REAR WINDSCREEN SEALANT	\$	na	100.00	}
1	WINDSCREEN MOULDING	\$	na	150.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
1	BOOT INNER TRIM CLIP	\$	na	45.00	
1SET	REAR BOOT OUTER GARNISH CLIP	\$	na	35.00	
1SET	REAR LAMP CLIP	\$	na	25.00	
1SET	REAR COMBINATION LAMP CLIP	\$	na	25.00	
1	Rear Bumper Protector	\$	na	100.00	
1SET	Rear licence plate with holder	\$	na	80.00	
1SET	LUGGAGE COMPARTMENT TRIM LH COVER CLIP	\$	na	35.00	
1SET	LUGGAGE COMPARTMENT TRIM RH COVER CLIP	\$	na	35.00	
TOTAL		\$		1,651.00	
TOTAL PARTS		\$		3,660.62	

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	100
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	na	170.00	X
To check steering geometry and computer wheel alignment	\$	na	220.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,000.00	300
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00	X

Trans-cab Auto Services Pte Ltd

LAD2102-004

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP7136H

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	na	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X

To reinstall rear bumper parking sensor.

\$ 170.00 *50¢*

Putty and spray painting of the affected portion.

\$ 2,000.00 *44¢*

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

\$ ~~170.00~~ *X*

TOTAL \$ 6,130.00

Over All Total \$ 9,790.62

**PART BY PART (REPAIR DAY) ~~10 DAYS~~
*3 days***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: