

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001606/KQD3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00005762000
Claimant Vehicle No :	SLR2387J	Insured Vehicle No :	CB9839S
Date of Loss:	18/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200639/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2387J	Engine No:	2ZR8029679
Make & Model:	TOYOTA C-HR HYBRID, 1.8 E G CVT (A)	Chassis No:	ZYX102010898
Reg. Date:	04/08/2017 (Man. Year: 2017)	Odometer:	291202 km
Colour:	Metallic Pearl White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,689.62	2,422.47	267.15	9.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	540.00	690.00	56.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,919.62	2,962.47	957.15	24.42
Approved Total (Overridden) (S\$)		2,350.00		
Nett Amount (S\$)	3,919.62	2,350.00	1,569.62	40.05

INSPECTION

Date of Assignment:	09/02/2021	
Date Inspected:	02/02/2021 Inspected At:	BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541 REPAIRER: LIAN HER MOTORS
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Feb 2021)	
Parts: M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLR2387J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT N/S HEADLAMP ASSY	Cut	1,804.30 FL	*1,804.30 FL	
2	1		*FRONT BUMPER	Mtg Cracked	985.70 FL	*830.00 FL	
3	1		*FRONT BUMPER LOWER GRILLE	Serviceable	115.10 FL	*- FL	
4	1		*FRONT BUMPER LOWER BUMPER	Cracked	499.30 FL	*489.00 FL	
5	1		*FRONT NO PLATE HOLDER	Serviceable	75.10 FL	*- FL	
6	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS	
7	20		*CLIP	Necessary	40.00 FS	*40.00 FS	
					Sub Total (S\$)	3,559.50	3,203.30
					- List Item Discount on L Items 25.00/25.00% (S\$)	869.88	780.83
					Total Parts (S\$)	2,689.62	2,422.47

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING ETC	New	600.00	300.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	600.00	220.00
3	CHECK AND RECONNECT WIRING	New	30.00	20.00
			Gross Labour Cost (S\$)	540.00
			1,230.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >