

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Park 2 Singapore 569541
H/p 91082728

Fax : 64816131

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #15-00
Springleaf Tower
Singapore 079909

Not Notified
61 Days @ 2350k
Insurance After Paint
2 days

Vehicle No : SLR 2387 J
Make : Toyota C-HR
Year : 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front n/s headlamp assy		<i>CU</i> \$1,804.30 ✓
1 pc	Front bumper <i>830</i>		<i>mycom</i> \$985.70 ✓
1 pc	Front bumper lower grille		<i>inc</i> \$115.10 X
1 pc	Front bumper lower bumper <i>489</i>		<i>cur</i> \$499.30 ✓
1 pc	Front no plate holder		<i>in</i> \$75.10 X
			\$3,479.50
Less 25 %			\$869.88
			\$2,609.62

S Nett

1 pc	Front no plate		<i>nd</i> \$40.00 ✓
20 pcs	Clip	\$2.00	<i>in</i> \$40.00 ✓
			\$80.00

Labour Charges

Remove/renew the above parts including knocking, welding etc.	\$600.00	<i>300k</i>
To putty & spray paint on accident affected portion.	\$600.00	<i>220k</i>
Check and reconnect wiring.	\$30.00	<i>20k</i>
Total	<u>\$3,919.62</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: