

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR 9062M

LAD2102-001

*Not Authorized
Permy B4 paint*

Vehicle No.: *SMR 9062M*
 Chassis No.: *JTDKB3FU503091053* **02 FEB 2021**
 Vehicle Make: *TOYOTA*
 Vehicle Model: *PRIUS*
 Date of Accident : *31.1.2021*
 Third Party Insurer : *EQ*
 Date of Registration: *30/1/2020*

SMR 9062M
JTDKB3FU503091053
TOYOTA
PRIUS
31.1.2021
EQ
30/1/2020

PART	
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	RETAINER, REAR BUMPER SIDE, LH
1	RETAINER, REAR BUMPER SIDE, RH
1	REFLECTOR ASSY, REFLEX, LH
1	REFLECTOR ASSY, REFLEX, RH
1	PANEL SUB-ASSY, BACK DOOR
1	COVER, REAR COMBINATION LAMP, RH
1	COVER, REAR COMBINATION LAMP, LH
1	BOARD ASSY, BACK DOOR TRIM
1	WEATHERSTRIP, BACK DOOR
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH
1	BOARD, BACK DOOR TRIM
1	LENS & BODY, REAR COMBINATION LAMP, LH
1	LENS & BODY, REAR COMBINATION LAMP, RH
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
1	LAMP ASSY, REAR, LH
1	LAMP ASSY, REAR, RH
1	PANEL ASSY, DECK TRIM SIDE, RH
1	COVER, FRONT BUMPER
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER

LIST	
\$	<i>Bulcom</i> 485.60 ✓
\$	<i>B4</i> 332.70 ✓
\$	<i>RU</i> 22.00 ✓
\$	<i>B4</i> 374.50 ✓
\$	<i>NSP</i> 132.60 X
\$	<i>NSP</i> 132.60 X
\$	<i>Sm</i> 39.00 X
\$	<i>PER</i> 39.00 ✓
\$	<i>R</i> 1,147.80 X
\$	<i>Sm</i> 69.90 X
\$	<i>Sm</i> 69.90 X
\$	<i>Sm</i> 259.20 X
\$	<i>Sm</i> 372.30 X
\$	<i>Sm</i> 56.50 X
\$	<i>Sm</i> 225.20 X
\$	<i>Sm</i> 339.60 X
\$	<i>Sm</i> 339.60 X
\$	<i>Sm</i> 261.00 X
\$	<i>Sm</i> 261.00 X
\$	<i>Sm</i> 293.60 X
\$	<i>Sm</i> 293.60 X
\$	<i>Sm</i> 355.90 X
\$	<i>Per/Res</i> 521.00 ✓
\$	<i>Sm</i> 110.50 X
\$	<i>R</i> 716.60 X

Trans-cab Auto Services Pte Ltd

LAD2102-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR 9062M

1 REINFORCEMENT, FRONT BUMPER, NO.2	\$	R	246.10	X
1 ABSORBER, FRONT BUMPER, LOWER	\$	Sm	132.70	X
1 ABSORBER, FRONT BUMPER ENERGY	\$	Sm	80.20	X
1 SUPPORT, FRONT BUMPER SIDE, RH	\$	Sm	80.10	X
1 SUPPORT, FRONT BUMPER SIDE, LH	\$	Sm	82.30	X
1 EXTENSION, FRONT BUMPER, RH	\$	Sm	120.10	X
1 EXTENSION, FRONT BUMPER, LH	\$	Sm	120.10	X
1 COVER, FRONT BUMPER HOLE, LH	\$	Sm	30.20	X
1 COVER, FRONT BUMPER HOLE, RH	\$	M/R	30.20	✓
1 LAMP ASSY, FOG, LH	\$	Sm	237.10	X
1 LAMP ASSY, FOG, RH	\$	Sm	237.10	X
1 UNIT ASSY, HEADLAMP, LH	\$	Sm	2,637.60	X
1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	Sm	3,772.50	X
1 UNIT ASSY, HEADLAMP, RH	\$	Sm	2,637.60	X
1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	Sm	3,772.50	X
1 GRILLE SUB-ASSY, RADIATOR	\$	Not in	422.50	✓
1 GRILLE, RADIATOR, LOWER NO.1	\$	Sm	178.60	} X
1 EMBLEM ASSY, RADIATOR GRILLE	\$	Sm	105.80	
1 GRILLE, RADIATOR	\$	Sm	160.50	
1 HOOD SUB-ASSY	\$	R	983.10	
1 HINGE ASSY, HOOD, LH	\$	R	58.90	
1 HINGE ASSY, HOOD, RH	\$	R	58.90	
1 BRACE, HOOD LOCK SUPPORT	\$	R	78.30	
1 GUIDE, RADIATOR AIR, NO.1 LH	\$	Sm	69.90	
1 GUIDE, RADIATOR AIR, NO.1 RH	\$	Sm	65.30	
1 GUIDE, RADIATOR AIR, NO.3	\$	Sm	112.70	
1 SEAL, RADIATOR TO SUPPORT, NO.3	\$	Sm	32.40	
1 SEAL, RADIATOR TO SUPPORT, NO.2	\$	Sm	32.60	
1 INLET, AIR CLEANER, NO.3	\$	Sm	42.10	
1 INLET, AIR CLEANER, NO.2	\$	Sm	112.70	
1 JAR ASSY, WINDSHIELD WASHER	\$	Sm	219.10	

TOTAL	\$	24,201.00
25%	\$	6,050.25
	\$	18,150.75

Trans-cab Auto Services Pte Ltd

LAD2102-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR 9062M

Special Nett

1SET PARKING AID	\$	Shot	700.00	2000m
1SET REAR BUMPER CLIP	\$	na	85.00	500m
2 REAR WINDSCREEN SEALANT	\$	na	150.00	800m
1 WINDSCREEN MOULDING	\$	na	200.00	✓
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	300m
1 REAR TAILGATE TOYOTA LOGO	\$	na	47.90	✓
1 REAR TAILGATE WORDING 'PRIUS'	\$	na	54.60	✓
1 REAR TAILGATE WORDING 'HYBRID'	\$	na	54.60	✓
1 REAR BUMPER PROTECTOR	\$	NSP	180.00	X
2 SEAM SEALANT	\$	na	250.00	X
1SET BUMPER CLIP FRT	\$	na	80.00	500m
1 FRONT NUMBER PLATE WITH MOULDING	\$	na	200.00	450m
1SET CLIP, FRONT FENDER LINER	\$	na	70.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	na	70.00	X
1SET REAR BUMPER RETAINER CLIP	\$	na	70.00	X
1 FRT NUMBER PLATE WITH HOLDER	\$	na	190.00	X
1SET REAR COMBINATION LAMP CLIP	\$	na	55.00	X
1 END PANEL TRIM CLIP	\$	na	60.00	X
1 REAR SPOILER CLIP	\$	na	60.00	X

TOTAL \$ 2,707.10

TOTAL PARTS \$ 20,857.85

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ 380.00 501

To transfer of Front Bumper fittings, attachments and perform water seepage test. \$ na 170.00 X

Trans-cab Auto Services Pte Ltd

LAD2009-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR 9062M

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	700
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	280.00	180
Putty And Spray Painting Of The Affected Portion.	\$	2,000.00	1100
To reinstall rear bumper parking sensor.	\$	170.00	50
To Check Electrical Lighting Concerned.	\$	170.00	40
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To remove and refit rear exhaust pipe to facilitate bodywork repair.	\$	170.00	X

TOTAL	\$	6,700.00
Over All Total	\$	27,557.85
(PART-BY-PART) Repair Days		-10 DAYS
		7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: