

ASS. REC. BY:

REF: EG /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: Tans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1:31% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMR 9062M Regn: 01, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1798

Colour: M. White Red A/C: Insured / Std / NI / NA

Sp. Reading: 10662 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU 503091053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Poilun

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 3/1/21 D.O.I. 2/2/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

2 14
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Got BI</u>

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____

S - RS - SI

Partials

Others

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR 9062M

LAD2102-001

*Not Authorized
Permy BQ part*

Vehicle No.:
Chassis No.: **Q2 FEB 2021**
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SMR 9062M
JTDKB3FU503091053
TOYOTA
PRIUS
31.1.2021
EQ
30/1/2020

PART

LIST

1 COVER, REAR BUMPER	\$	<i>Autem</i>	485.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>By</i>	332.70	✓
1 COVER, REAR BUMPER, LOWER	\$	<i>nu</i>	22.00	✓
1 GUARD, REAR BUMPER, CENTER	\$	<i>By</i>	374.50	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$	<i>NSP</i>	132.60	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	<i>NSP</i>	132.60	X
1 REFLECTOR ASSY, REFLEX, LH	\$	<i>Sm</i>	39.00	X
1 REFLECTOR ASSY, REFLEX, RH	\$	<i>Per</i>	39.00	✓
1 PANEL SUB-ASSY, BACK DOOR	\$	<i>n</i>	1,147.80	X
1 COVER, REAR COMBINATION LAMP, RH	\$	<i>Sm</i>	69.90	X
1 COVER, REAR COMBINATION LAMP, LH	\$	<i>Sm</i>	69.90	X
1 BOARD ASSY, BACK DOOR TRIM	\$	<i>Sm</i>	259.20	X
1 WEATHERSTRIP, BACK DOOR	\$	<i>Sm</i>	372.30	X
1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>Sm</i>	56.50	X
1 BOARD, BACK DOOR TRIM	\$	<i>Sm</i>	225.20	X
1 LENS & BODY, REAR COMBINATION LAMP, LH	\$	<i>Sm</i>	339.60	X
1 LENS & BODY, REAR COMBINATION LAMP, RH	\$	<i>Sm</i>	339.60	X
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$	<i>Sm</i>	261.00	X
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	<i>Sm</i>	261.00	X
1 LAMP ASSY, REAR, LH	\$	<i>Sm</i>	293.60	X
1 LAMP ASSY, REAR, RH	\$	<i>Sm</i>	293.60	X
1 PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>Sm</i>	355.90	X
1 COVER, FRONT BUMPER	\$	<i>Autem</i>	521.00	✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>Sm</i>	110.50	X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	<i>n</i>	716.60	X

Trans-cab Auto Services Pte Ltd

LAD2102-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR 9062M

1 REINFORCEMENT, FRONT BUMPER, NO.2	\$	R	246.10	X
1 ABSORBER, FRONT BUMPER, LOWER	\$	Sm	132.70	X
1 ABSORBER, FRONT BUMPER ENERGY	\$	Sm	80.20	X
1 SUPPORT, FRONT BUMPER SIDE, RH	\$	Sm	80.10	X
1 SUPPORT, FRONT BUMPER SIDE, LH	\$	Sm	82.30	X
1 EXTENSION, FRONT BUMPER, RH	\$	Sm	120.10	X
1 EXTENSION, FRONT BUMPER, LH	\$	Sm	120.10	X
1 COVER, FRONT BUMPER HOLE, LH	\$	Sm	30.20	X
1 COVER, FRONT BUMPER HOLE, RH	\$	Sm	30.20	✓
1 LAMP ASSY, FOG, LH	\$	Sm	237.10	X
1 LAMP ASSY, FOG, RH	\$	Sm	237.10	X
1 UNIT ASSY, HEADLAMP, LH	\$	Sm	2,637.60	X
1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	Sm	3,772.50	X
1 UNIT ASSY, HEADLAMP, RH	\$	Sm	2,637.60	X
1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	Sm	3,772.50	X
1 GRILLE SUB-ASSY, RADIATOR	\$	Mod/Gr	422.50	✓
1 GRILLE, RADIATOR, LOWER NO.1	\$	Sm	178.60	} X
1 EMBLEM ASSY, RADIATOR GRILLE	\$	Sm	105.80	
1 GRILLE, RADIATOR	\$	Sm	160.50	
1 HOOD SUB-ASSY	\$	R	983.10	
1 HINGE ASSY, HOOD, LH	\$	R	58.90	
1 HINGE ASSY, HOOD, RH	\$	R	58.90	
1 BRACE, HOOD LOCK SUPPORT	\$	R	78.30	
1 GUIDE, RADIATOR AIR, NO.1 LH	\$	Sm	69.90	
1 GUIDE, RADIATOR AIR, NO.1 RH	\$	Sm	65.30	
1 GUIDE, RADIATOR AIR, NO.3	\$	Sm	112.70	
1 SEAL, RADIATOR TO SUPPORT, NO.3	\$	Sm	32.40	
1 SEAL, RADIATOR TO SUPPORT, NO.2	\$	Sm	32.60	
1 INLET, AIR CLEANER, NO.3	\$	Sm	42.10	
1 INLET, AIR CLEANER, NO.2	\$	Sm	112.70	
1 JAR ASSY, WINDSHIELD WASHER	\$	Sm	219.10	

TOTAL	\$	24,201.00
25%	\$	6,050.25
	\$	18,150.75

Trans-cab Auto Services Pte Ltd

LAD2102-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR 9062M

Special Nett

1SET PARKING AID	\$	Short	700.00	2000m
1SET REAR BUMPER CLIP	\$	na	85.00	500m
2 REAR WINDSCREEN SEALANT	\$	na	150.00	800m
1 WINDSCREEN MOULDING	\$	na	200.00	—
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	300m
1 REAR TAILGATE TOYOTA LOGO	\$	na	47.90	—
1 REAR TAILGATE WORDING 'PRIUS'	\$	na	54.60	—
1 REAR TAILGATE WORDING 'HYBRID'	\$	na	54.60	—
1 REAR BUMPER PROTECTOR	\$	NSA	180.00	X
2 SEAM SEALANT	\$	na	250.00	X
1SET BUMPER CLIP FRT	\$	na	80.00	500m
1 FRONT NUMBER PLATE WITH MOULDING	\$	By	200.00	450m
1SET CLIP, FRONT FENDER LINER	\$	na	70.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	na	70.00	X
1SET REAR BUMPER RETAINER CLIP	\$	na	70.00	X
1 FRT NUMBER PLATE WITH HOLDER	\$	na	190.00	X
1SET REAR COMBINATION LAMP CLIP	\$	na	55.00	X
1 END PANEL TRIM CLIP	\$	na	60.00	X
1 REAR SPOILER CLIP	\$	na	60.00	X

TOTAL \$ 2,707.10

TOTAL PARTS \$ 20,857.85

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ 380.00 501

To transfer of Front Bumper fittings, attachments and perform water seepage test. \$ na 170.00 X

Trans-cab Auto Services Pte Ltd

LAD2009-001

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMR 9062M

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	700
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	280.00	180
Putty And Spray Painting Of The Affected Portion.	\$	2,000.00	1100
To reinstall rear bumper parking sensor.	\$	170.00	50
To Check Electrical Lighting Concerned.	\$	170.00	40
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To remove and refit rear exhaust pipe to facilitate bodywork repair.	\$	170.00	X

TOTAL \$ 6,700.00
Over All Total \$ 27,557.85
(PART BY-PART) Repair Days ~~10~~ 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999



T/20210201/2128

1 of 3

Report No. T/20210201/2128

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/02/2021 19:08	Vide Report No.: T/20210131/7035	Station Diary No.: 106
--	-------------------------------------	---------------------------

Informant's Particulars			
Name of Informant: CHAN PENG FAI		Address: APT BLK 265 YISHUN STREET 22 #03-216 SINGAPORE 760265	
ID Type / ID No.: NRIC NO / S16018921		Contact No.: Home/Office:	Mobile: 98785093
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 57	Date of Birth: 15/03/1963	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: DRIVER		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/01/2021 15:25	Type of Location: Flyover
Location: CENTRAL EXPRESSWAY				
Lamp Post Number: 98				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Vehicle Chain Collision			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJF7685C	Car	HONDA	STREAM 1.8X A	Black		0
SLU9027L	Car	OPEL	ASTRA HB 1.0 AT	White		0
SMR9062M	Car	TOYOTA	PRIUS 5DR HATCHBAC K (AUTO)	Red		0



**SINGAPORE
POLICE FORCE**



T/20210201/2128

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 3

Report No. T/20210201/2128

CONTINUATION OF REPORT

Brief Details.

Brief Details.

- 1) I had lodged a Traffic Police Reference T/20210131/7035. I would like to add on more information for the report that I lodged.
- 2) On 31 January 2021 at about 1525hrs, My vehicle (SMR9062M) along CTE towards SLE near LP 98 on the second lane from the right. There was a vehicle (SJF7685C) stopped in-front of my vehicle due to the traffic.
- 3) I stopped my vehicle gradually. However there was a vehicle (SLU9027L) came from the rear and knocked onto my vehicle causes my vehicle to moved forward and knocked onto the vehicle (SJF7685C) in-front of me.
- 4) All of us checked on the vehicle and exchanged particulars.
- 5) I went to the clinic and was given 4 days of medical leave and two of my passengers were given 3 days of medical leave.

NOTE: (A) Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the Certificate with you now, please fax a copy to 654 74855 stating the report number as reference.

Signature Of Officer Recording The Report Sgt CAN YIBI LEONG, ALASTAIR	Signature Of Driver
Signature Of Interpreter Not applicable	Date/TIME 31/01/2021 19:00
Officer In Charge Of Case Sgt S MURUGAN RIZWAN BIN KAMALUDIN Contact No: 89470195	Classification Of Case