

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 05 Apr 2021

Preliminary Advice

Insured Vehicle No : GBG296C
TP Vehicle No : SJG3243R
Make : HONDA CIVIC
Date of Inspection : 03/02/2021
Inspection At : N-51 AUTOMOTIVE PTE LTD (KAKI BUKIT AUTOHUB) (HQ)
KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18
SINGAPORE 417921

Accident Date : 01/02/2021
Assignment Date : 28/03/2021
Est. Duration of Repair : 6

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 9,945.64 |
| Revised Amount | :S\$ | 7,054.96 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 7,054.96 |
| Lump Sum Repair | :S\$ | 5,600.00 |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on WP