

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

CHUA CHIN MOH  
 BLK 189C RIVERVALE DRIVE #07-994  
 SINGAPORE 543189

Contact : 82821448

*TP Chua.  
Denise.*

## ESTIMATE

Repair Code : CLM15174  
 Date in : 01/02/2021  
 Vehicle Num. : SJG3243R  
 Model : HONDA CIVIC 1.8L A  
 Chassis/Eng# : JHMFD16308S216407/R18A13036318

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Dented</i>	1	610.70	✓ 610.70
REAR BOOTLID '1.8' EMBLEM	1	38.00	✓ 38.00
REAR BOOTLID 'CIVIC' EMBLEM	1	39.00	✓ 39.00
REAR BOOTLID 'I-VTEC' EMBLEM	1	34.10	✓ 34.10
REAR BOOTLID 'LOGO' EMBLEM	1	39.00	✓ 39.00
REAR BOOTLID HINGES L/R <i>new</i>	2	48.60	+ 97.20
REAR BOOTLID INNER LOWER RUBBER STOPPER L/R <i>new</i>	2	12.50	+ 25.00
REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i>	2	18.50	+ 37.00
REAR BOOTLID INNER TRIM BOARD <i>new</i>	1	133.70	+ 133.70
REAR BOOTLID LOCK STRIKER <i>new</i>	1	27.50	+ 27.50
REAR BOOTLID MECHANISM LOCK <i>Dented</i>	1	194.50	✓ 194.50
REAR BOOTLID NUMBER PLATE GARNISH <i>could</i>	1	121.60	✓ 121.60
REAR BOOTLID NUMBER PLATE LAMP L/R <i>new</i>	2	15.50	+ 31.00
REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R <i>new</i>	2	15.20	✓ 30.40
REAR BOOTLID REFLECTOR L/R <i>lit</i>	2	178.10	✓ 356.20
REAR BOOTLID WEATHER STRIP <i>lit</i>	1	97.60	✓ 97.60
REAR BUMPER <i>Dented</i>	1	638.00	✓ 638.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	32.00	✓ 64.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

CHUA CHIN MOH  
 BLK 189C RIVERVALE DRIVE #07-994  
 SINGAPORE 543189

Contact : 82821448

## ESTIMATE

Repair Code : CLM15174  
 Date in : 01/02/2021  
 Vehicle Num. : SJG3243R  
 Model : HONDA CIVIC 1.8L A  
 Chassis/Eng# : JHMFD16308S216407/R18A13036318

REAR END PANEL <i>Dented</i>	1	330.50	✓	330.50
REAR END PANEL INNER TOP GARNISH <i>Del'd</i>	1	69.00	✓	69.00
REAR FENDER INNER TRIM BOARD L/R <i>Del'd</i>	2	145.90	✓	291.80
REAR FLOOR PANEL TOP BOARD COVER <i>Del'd</i>	1	316.00	✓	316.00
REAR LH FENDER INNER AIR VENT <i>neu</i>	1	24.30	✗	24.30
REAR TAILLAMP INNER BLACK GASKET L/R <i>neu</i>	2	10.50	✓	21.00
REAR TAILLAMP INNER PANEL L/R <i>Reps</i>	2	65.70	+	131.40
REAR TAILLAMP L/R <i>ut</i>	2	305.00	✓	610.00
REAR TAILLAMP LOWER BRACKET L/R <i>Best</i>	2	14.90	✓	29.80
Subtotal before discount				4,438.30
Percentage discount 20%				887.66
<b>Sub-total 1</b>				<b>3,550.64</b>
REAR BOOTLID CAMERA <i>Dented</i>	1	800.00	<del>380</del>	<del>800.00</del>
REAR BOOTLID INNER TRIM BOARD CLIPS - SET <i>neu</i>	1	50.00	<del>30</del>	<del>50.00</del>
REAR BOOTLID NUMBER PLATE	1	25.00	+	25.00
REAR BOOTLID NUMBER PLATE HOLDER <i>neu</i>	1	50.00	+	50.00
REAR BOOTLID TOP SPOILER <i>could</i>	1	1000.00	<del>700</del>	<del>1,000.00</del>
REAR BUMPER CLIPS - SET <i>neu</i>	1	80.00	<del>30</del>	<del>80.00</del>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

CHUA CHIN MOH  
 BLK 189C RIVERVALE DRIVE #07-994  
 SINGAPORE 543189

Contact : 82821448

## ESTIMATE

Repair Code : CLM15174  
 Date in : 01/02/2021  
 Vehicle Num. : SJG3243R  
 Model : HONDA CIVIC 1.8L A  
 Chassis/Eng# : JHMFD16308S216407/R18A13036318

REAR BUMPER LOWER SPOILER	<i>Red</i>	1	900.00	<i>580</i> <del>900.00</del>
REAR BUMPER REVERSE SENSOR - SET	<i>Damaged</i>	1	280.00	<i>200</i> <del>280.00</del>
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>New</i>	1	50.00	<i>10</i> <del>50.00</del>
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	<i>New</i>	2	50.00	<i>60</i> <del>100.00</del>
REAR FLOOR PANEL INSULATOR	<i>New</i>	1	300.00	<i>2030</i> <del>300.00</del>
REAR TAILLAMP CLIPS L/R - SET	<i>New</i>	2	30.00	<i>40</i> <del>60.00</del>
Subtotal before discount				3,695.00
Percentage discount 0%				0.00
<b>Sub-total 2</b>				3,695.00
<b>Parts-total</b>				7,245.64

## LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector	✓	80.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	✓	80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>60</i>	<del>120.00</del>
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	<i>1880</i>	<del>1,200.00</del>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>800</i>	<del>1,100.00</del>
To apply anti-rust chemical on repaired and replaced panel.	<i>60</i>	<del>120.00</del>
<b>Labour Total</b>		<b>2,700.00</b>
<b>Parts &amp; Labour Total</b>		<b>9,945.64</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

page 3

*Adrian Lij*  
*1/5 03/02/21*  
*06 Days*  
*total: 7054.96*  
*L/s: 5.6k ✓*