



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD  
C/O AREDA ADJUSTERS PL  
229 MOUNTBATTEN ROAD #01-10  
MOUNTBATTEN SQUARE SINGAPORE 398007

Ref: CS/AAP21001625/R1vf3e2

Date: 08/03/2021

Code: TMI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	PUBLIC LIABILITY	<b>Veh. Inspected</b>	SLW 888S
<b>Policy No.</b>	2195597/BC	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	G2100124	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	BRANDON CHUA	<b>Assign Date</b>	02/02/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	BENTLEY FLYING SPUR V8 S S/R	<b>c.c</b>	3993
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	SCBEE53W7HC066059	<b>Colour</b>	BLUE
<b>Odometer</b>	10237 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	275/35 ZR21	PIRELLI	6 mm
<b>L/H Front Tyre</b>	275/35 ZR21	PIRELLI	6 mm
<b>R/H Rear Tyre</b>	275/35 ZR21	PIRELLI	6 mm
<b>L/H Rear Tyre</b>	275/35 ZR21	PIRELLI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND ROOF TOP.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	03/02/2021	<b>Inspection Date</b>	09/02/2021
<b>Survey held at</b>	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.		

### 5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**