

PAIR ESTIMATE*

VEHICLE NO SHD3020G

DATE 01/02/21 12:00 AM

MAKE :

CHIANG /NTUC

MODEL HYU- I40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	BONNET HINGE RH			\$41.00
1	HEADLAMP RH			\$1,388.00
1	FENDER RH			\$663.00
1	FRONT BUMPER SIDE RH /LH		\$14.30	LHX \$28.60
1	FRONT BUMPER BRACKET LH/RH		\$24.60	LHX \$49.20
1	FRONT BUMPER ASSY			\$1,052.20
1	FRONT RAD GRILLE			1110.10 \$1,480.00
	SUB TOTAL		3550.30	\$4,702.00
	20.00%			\$940.40
	DISCOUNTED TOTAL		2840.24	\$3,761.60
1	FRONT NUMBER W/HOLDER			\$50.00
		45		\$45.00
	Labour Charge			
	Panel Beating			\$720.00
	Spray Painting Charge			\$600.00
	Check wiring	950		\$60.00
	Tuff kote			\$60.00
	TOTAL LABOUR	2835.24		\$1,440.00
	ESTIMATE TOTAL	45 \$3,000		\$5,246.60
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alteration of the estimate is allowed
- Occupant's vehicle must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Tanphie 92495789
2/2/21 4pm
1/3 Resurvey after repair
tanphie@lkhauto.com
2-3 days.

WnHole