

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 02/02/2021
TP Veh Reg No: SMS4740S

Estimate No: EST2100035

Date: 03 Feb 2021

Veh Reg No: **SJH5134D**
Make/Model: TOYOTA ISIS 1.8LX A
Chasis No: ZNM100056142
Reg. Date: 12/08/2008
Your Ref No: SMS4740S

Estimate Repair Cost to Vehicle No :SJH5134D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	1,567.40	
2	1 PC BOOT LID LOGO	99.40	
3	1 PC BOOT LID CHROME MOULDING	287.60	
4	2 PCS REAR NUMBER PLATE LAMP	156.40	
5	1 PC BOOT LID RUBBER	363.40	
6	1 PC BOOT LID OUTER OPENER HANDLE	198.70	
7	1 PC BOOT LID LOCK	470.50	
8	1 PC BOOT LID LOCK CHECKER	66.70	
9	1 PC BOOT LID TRIM	466.20	
10	1 PC BOOT LID HOLDING HANDLE	38.90	
11	1 PC REAR PANEL	616.70	
12	1 PC REAR PANEL TRIM	253.90	
13	1 PC REAR FENDER TRIM RH	712.20	
14	1 PC REAR FENDER TRIM LH	712.20	
15	1 PC REAR BUMPER	1,236.90	
16	2 PCS REAR BUMPER BRACKET	134.80	
17	2 PCS REAR BUMPER SIDE RETAINER	143.00	
18	1 PC REAR TOWING COVER	81.40	
19	1 PC REAR BUMPER SIDE LAMP RH	414.20	
20	1 PC REAR BUMPER SIDE LAMP - LH	414.20	
21	1 PC SPARE TYRE LOCK	144.50	
22	1 PC REAR ANTENNA SENSOR	166.90	
23	1 PC EXHAUST PIPE	992.60	
24	2 PCS EXHAUST PIPE MOUNTING	62.00	
		<u>9,800.70</u>	
		Less 25%	<u>2,450.18</u>
			7,350.57
	Special Net		
25	1 PC REAR WINDSCREEN SEAL	60.00	
26	1 PC REAR WINDSCREEN SEALANT	60.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 02/02/2021
TP Veh Reg No: SMS4740S

Estimate No: EST2100035
Date: 03 Feb 2021

Veh Reg No: SJH5134D
Make/Model: TOYOTA ISIS 1.8LX A
Chasis No: ZNM100056142
Reg. Date: 12/08/2008
Your Ref No: SMS4740S

Estimate Repair Cost to Vehicle No :SJH5134D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
27	1 PC REAR NUMBER PLATE	50.00	
28	1 PC REVERSE CAMERA	480.00	
29	1 SET BOOTLID TRIM CLIPS	40.00	
30	1 SET REAR PANEL TRIM CLIPS	40.00	
31	1 SET REAR FENDER TRIM CLIPS RH	40.00	
32	1 SET REAR FENDER TRIM CLIPS LH	40.00	
33	1 SET REAR BUMPER CLIPS	60.00	
34	1 SET REVERSE SENSORS	280.00	
		1.150.00	1.150.00
	Labour		
35	1 TO CHECK WIRING	50.00	
36	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
37	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
38	1 TO REMOVE AND REFIT REAR VIEW CAMERA	80.00	
39	1 TO REMOVE AND REFIT INNER TRIM	150.00	
40	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00	
41	1 TO SPRAY UNDERSEAL	120.00	
42	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
43	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00	
44	1 (REAR) TO SPRAY PAINTING	1,300.00	
45	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,400.00	
		3.610.00	3.610.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 02/02/2021
TP Veh Reg No: SMS4740S

Estimate No: EST2100035

Date: 03 Feb 2021

Veh Reg No: **SJH5134D**
Make/Model: TOYOTA ISIS 1.8LX A
Chasis No: ZNM100056142
Reg. Date: 12/08/2008
Your Ref No: SMS4740S

Estimate Repair Cost to Vehicle No :SJH5134D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 12,110.57
	Add GST @ 7%		847.74
	Total Amount Payable		<u>S\$ 12,958.31</u>

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND NINE HUNDRED FIFTY EIGHT AND CENTS THIRTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE