

12/02/2020

REF: CS/CTI21001644/Kvd3

Special Instruction:

ASS. REC. BY:

SURVBY

KENNETH

ASSIGNMENT (Office)

Merimen

From (Person):

CECILIA LOW

of

CTI

Date/Time: 03/02/2021@3.09PM

Estimated Cost:

Bill to:

OD ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 409Y

Insured: SMX 3632B

at Workshop m/s

TONG LUCK AUTO

Tel: 6250 0088

of

160 SIN MING DRIVE# 07-01/06

Policy No: DMPCSNW00011462100

Claim No: SNM21D200645/C02/L OWCT

Sum Insured:

Excess:

D.O.A. 29/01/2021

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 3.51pm@3/02/2021

Person Contacted: CANDY

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate	Repairer agreed to survey on 04/02/2021
	SLC 409Y-X	
	SMX 3632B-X	
5/2/21	Send IA via merimen	
19/2/21	Kenneth confirmed LS \$6550 (Red 5323.30,44%)	