

ASS. REC. BY:

REF:

CTZ/ 21 061644/Kd

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 4094

Yr Regn:

16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q7

c.c

1984

Colour

m.d. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

44539

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAAU 222 4m 7GD 042809

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

255/55R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

29/1/21

D.O.I.

4/2/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 19/2/21-Typist

Report Format: Merimen

Lump Sum / I.B.I: (\$ LS \$6550

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SMX3632B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 29/01/2021

TP VEH REG NO : SMX3632B

ESTIMATE

NO : QUOT202102-000010(00)

DATE : 02/02/2021

POLICY NO : 999995580

VEH REG NO : SLC409Y

MAKE/MODEL : AUDI Q7 2.0 TFSI QU (252 BHP)

CHASSIS NO : WAUZZZ4M7GD042809

ENGINE NO : CYR006983

REG. DATE : 2016

Not Authorized

11 Day 8

Runny After Paint

04/02/2021

Estimate Repair Cost to Vehicle No : SLC409Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Tailgate <i>(Aluminium)</i>	1	<i>nu</i> 3,839.35	3,839.35 ✓
2 Tailgate center logo	1	93.65	<i>nu</i> 93.65 ✓
3 Tailgate 'Q7' emblem	1	72.30	<i>nu</i> 72.30 ✓
4 Tailgate 'TFSI quattro' emblem	1	72.30	<i>nu</i> 72.30 ✓
5 Rear end panel	1	487.15	<i>n</i> 487.15 X
6 Rear bumper (upper)	1	<i>bu</i> 901.95	901.95 ✓
7 Rear bumper (lower)	1	<i>cm</i> 1,181.75	1,181.75 ✓
8 Rear bumper reinforcement	1	993.55	993.55 ?
9 Rear bumper sponge	1	102.00	102.00 ?
10 Rear bumper tow cover - LH	1	41.10	<i>nu</i> 41.10 ✓
11 Rear bumper reflector - LH	1	269.90	<i>cm</i> 269.90 ✓
12 Rear bumper sensor	2	208.85	<i>bu</i> 417.70 ✓
13 Rear bumper sensor seals	4	6.00	<i>nu</i> 24.00 ✓
14 Rear bumper lower spoiler	1	853.65	<i>cm</i> 853.65 ✓
15 Rear bumper clips	15	5.50	<i>nu</i> 82.50 ✓
16 Rear exhaust end chrome - LH	1	348.55	<i>bu</i> 348.55 X
			9,781.40
		Less 10%	978.10
			8,803.30
SPECIAL NET			
17 Rear windscreen sealant	1	60.00	<i>nu</i> 60.00 <i>405n</i>
			60.00
LABOUR			
18 To remove and refit rear windscreen glass	1	150.00	150.00 <i>120k</i>
19 To transfer damaged tailgate interior mechanism to new tailgate	1	120.00	120.00 <i>60k</i>
20 To remove and refit rear bumper sensor	1	100.00	100.00 <i>60k</i>
21 To check and rectify wiring system	1	80.00	80.00 <i>20k</i>
22 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 <i>500k</i>
23 To putty and spray paint on affected areas	1	1,200.00	1,200.00 <i>800k</i>
24 To apply rust-proofing on replaced and repaired panels	1	160.00	<i>nu</i> 160.00 X
			3,010.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/01/2021 10:44 (SGT)
Date of Accident	29/01/2021 08:30 (SGT)
Exact Location of Accident	1 Woodleigh Ln, Singapore 357684
Additional Location Information	STAMFORD AMERICAN INTERNATIONAL SCHOOL (WOODLEIGH LANE) SCHOOL COMPOUND
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC409Y
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No	1XXXXX778Z
Email Address	benny.chong@daimler.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	(Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer	Audi
Model	Q7
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	NA

DRIVER

Name of Driver	RUBEN MANNIEN
Passport No/FIN	GXXXX456N
Date Of Birth	27/08/1972

Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

Indoor
25/06/2014
6 YEARS AND 7 MONTHS
Male
(Phone) +65-85226011
-
ruben.mannien@allnex.com
556820 #10-01
-
-
No
Hirer
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

My vehicle was queuing at the school compound to drop off my daughter. After dropped off my daughter and I was still in the queue waiting for the clearance. Suddenly I felt a hard impact from behind and saw a vehicle had already hit onto my vehicle rear portion.


ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMX3632B
Vehicle Manufacturer Maserati
Vehicle Model GRANCABRIO SPORT
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car
Name of Driver SUN JINGRUO
NRIC No SXXXX311Z
Contact Number -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Stamford American International School

REFER TO ATTACHED STATEMENT.


A: SLC 409Y

B: SMX 3632B

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
AIZAM BIN ATAN

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: