



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /CHUA PENG GEE (CAI BINGYI) Reg No/Reg Date SMT2410C / 02/04/202 Date In/Mileage / 0 Chassis No KNAF3416ML5069636 Engine No G4FGKH755885 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	03/02/2021/ 15:46	BLE	261 / Edwin Caina	28536

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT ¹ BUMPER REPAIR / ALIGN RHF FENDER	400			1600.00
E PNT98000 RESpray FRT ¹ BUMPER & RHF ¹ FENDER (CCRS colour)				960.00
E PNT88000 REMOVE / REFIT AC COND & RADIATOR				100.00
M SUNDRY TOP UP AC GAS				80.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY RENEW RHF SPORT RIM , TRANSFER TYRE & WHEEL BALANCING				30.00
M SUNDRY SUPPLY RHF SPORT RIM -16" S8004				480.00
M SUNDRY Sundries				20.00
M COVER-FR BUMPER	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER	1.00	262.00	20.00	209.60
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
M MOULDING-FRONT BUMPER,RH	1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER,RH	1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER,RH	1.00	14.00	20.00	11.20
M ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60
M GUARD ASSY-FRONT WHEEL,RH	1.00	95.00	20.00	76.00
M LAMP ASSY-HEAD,RH	1.00	1219.00	20.00	975.20
M CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00	540.00

SURVEYOR NAME :

SURVEYOR SIGNATURE :

Confirm & accepted by

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• Authorized signatory and company stamp

DATE :

REMARKS :

7% GST on
Nett 5,924.80
5924.80

Total Payable

5,924.80

414.74

6,339.54

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.