



Co. Reg: 20135118W

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date : 2/2/2021

Total Pages : 1

TO: Lonpac Insurance Bhd
300, Beach Road, 07
The Concourse, #17-04
Singapore 199555

Our Customer : Ng Wei Tze

Vehicle No : **SJB215T**

Model : TOYOTA/LEXUS IS250

Manufacture Year : 2007

Date of Accident : 30/1/2021

Total Estimate Repair Days : 4

Attn : Motor Claim Department

Email : MT_CLAIMS@lonpac.com

Re: Repair Estimate For Third Party Claim against : GX8227B

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper	1	\$785.10	\$785.10	
2	Rear bumper clips	8	\$5.89	\$47.12	
3	Rear bumper side retainer - RH	1	\$81.70	\$81.70	
4	RH rear fender	1	\$603.70	\$603.70	
	Sub Total			\$1,517.62	
	Less 25%			\$379.41	
	Sub Total 1			\$1,138.22	
	Total Spare Parts			\$1,138.22	
B.	Labour				
1	To knock & straighten the damaged panels,remove & renew damaged parts,adjust & realign the same			\$600.00	
2	To check lighting and all wiring			\$80.00	
3	To rust proof all affected areas			\$80.00	
4	To re-install reverse camera			\$120.00	
5	To spray paint RH rear fender and RH rear bumper			\$600.00	
	Total Labour			\$1,480.00	
	Total Repair Cost			\$2,618.22	
	* The above quoted are exclusive of GST.				

Yours faithfully,

Venessa
f Auto N Cars Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommend	Authorize / Not Authorize
Before Paint	Yes / No
Signature	