



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65691056



ESTIMATE

GST Reg No : MR 8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10695/YUEN HO TIAN Reg No/Reg Date SMJ6305A / 14/03/201 Date In/Mileage / 0 Chassis No MMB5TA13AKH001202 Engine No 3A92UHN8611 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	03/02/2021/ 15:54	QUD	247 / DonBong	62604			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR ¹ BOOT LID, REAR SPOILER LIP, REAR ¹ BUMPER, REAR BODY KITS CUT/WELD REAR FLOOR PANEL, REAR ³ END PANEL. REPAIR RH ¹ REAR FENDER, REPAIR ¹ LH REAR FENDER					5x 450			3150.00
E PNT88000 REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK								2250
E PNT88000 REMOVE AND INSTALL PARKING ASSIST								120.00
E PNT88000 TO REMOVE AND INSTALL REAR BODY KITS AND REAR SPOILER LIP								60.00
E PNT98000 PAINT WORK SPRAY REAR FLOOR PANEL, REAR ¹ END PANEL, REAR ¹ BOOT LID, REAR SPOILER, REAR ¹ BUMPER, REAR ¹ BODY KITS, RH REAR FENDER, LH ¹ REAR FENDER AND AFFECTED PORTION					6x 350			160.00
M SUNDRY PERFORM RUST PREVENTION								3150.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								2190
M SUNDRY APPLY BODY SEALANT								40
M SUNDRY SUPPLY C&C LOGO								120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								30.00
M SUNDRY SUPPLY REAR PARKING SENSOR								120.00
M SUNDRY SUPPLY REAR NUMBER PLATE WITH FRAME								40.00
A 13900099 REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK								120.00
M SUNDRY								220.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10695/YUEN HO TIAN Reg No/Reg Date SMJ6305A / 14/03/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001202 Engine No 3A92UHN8611 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	03/02/2021/ 15:54	QUD	247 / DonBong	62604			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
SUNDRIES					1.00	956.00	23.00	736.12
M	FLOOR,RR	1 X NM			1.00	427	425.00	327.25
M	PANEL,RR END	1 - OR			1.00	195.00	23.00	150.15
M	BOARD,TRUNK ROOM FLOOR	1 - CRU			1.00	66.00	23.00	50.82
M	TRIM,RR END	1 - BR			1.00	96.00	23.00	73.92
M	ANT,KEYLESS OPERATION,RR	1 X NM			1.00	91.00	23.00	70.07
M	BUZZER,KEYLESS OPERATIO,RR	1 X NM			1.00	20.00	23.00	15.40
M	STRIKER,TRUNK LID LATCH	1 X NM			1.00	20.00	23.00	15.40
M	STRIKER,TRUNK LID LATCH	1 - CRU			1.00	157.00	23.00	120.89
M	WEATHERSTRIP,TRUNK LID	1 - CRU			1.00	795	791.00	609.07
M	PANEL,TRUNK LID	1 - CRU			1.00	21.00	23.00	16.17
M	MARK,ATTRAGE	1 - CRU			1.00	337	336.00	258.72
M	GARNISH,RR END PANEL	1 - CRU			1.00	337	335.00	257.95
M	LAMP ASSY,COMB,RR LH	1 - BR			1.00	335.00	23.00	257.95
M	LAMP ASSY,COMB,RR RH	1 - BR			1.00	23.00	23.00	17.71
M	REFLECTOR LH	1 X NM			1.00	23.00	23.00	17.71
M	REFLECTOR RH	1 X NM			1.00	51.00	23.00	39.27
M	LAMP ASSY,LICENSE PLATE	1 X NM			1.00	51.00	23.00	39.27
M	LAMP ASSY,LICENSE PLATE	1 X NM			1.00	30.00	23.00	23.10
M	DUCT,RR VENTILATOR	1 - CRU			1.00	40.00	23.00	30.80
M	COVER,RR VENTILATOR	1 - CRU			3.00	3.00	23.00	6.93
M	CLIP,GEARSHIFT CONTROL LIN	1 X NM			1.00	28.00	23.00	21.56
M	BRACKET,RR BUMPER,LH	1 - BR			1.00	28.00	23.00	21.56
M	BRACKET,RR BUMPER,RH	1 - BR			6.00	4.00	23.00	18.48
M	CLIP,FR BUMPER	1 - CRU			1.00	751	748.00	575.96
M	FACE,RR BUMPER	1 - CRU			1.00	1643.00	00.00	1643.00
M	ATTRAGE BODYKITS	1 - CRU						

Estimate

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 3/2/21, 4.00pm

DATE: 00-NM AL

REMARKS: Excess - ?

SURVEYOR NAME :

Steve CLKK

SURVEYOR SIGNATURE :

3/2/21, 4.00pm

DATE :

00-NM AL

REMARKS :

EXCISE - ?

Confirm & accepted by

P/P
 My B&L SKY
 9 days

Nett 13,255.23
 7% GST on 13255.23 927.87
Total Payable 14,183.10

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.