

III JP

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

19-Apr-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) WAGON REGN NO: SHC 6794 S

1 pc	Front o/s fender	\$	514.02 ✓
1 pc	Front o/s fender inner shield	\$	176.72 ?
1 pc	Front bumper	\$	811.11 RR
1 PC	Front bumper o/s side bracket	\$	32.51 ?
		\$	1,534.36
	Less 20%	\$	306.87
		\$	1,227.49
S/NETT			
1 set	Front bumper clips	\$	52.50 ?
1 pc	Front o/s fender sticker	\$	30.00 / nec
1 set	Front o/s feinder inner shield clips	\$	28.00 ?
	Sundry	\$	50.00 X 20
	To checl wheel alignment	\$	80.00 ? X
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front o/s door	\$	700.00 500
	To putty and spray painting on the front bumper, front o/s fender, front o/s door	\$	600.00 400
	To apply rustproofing on the repaired and replaced panels	\$	120.00 50
	Total	\$	<u>2,887.99</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NAZ
LKK 20/84/16
P/E
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: