

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001660/AEA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993703
Claimant Vehicle No :	FBD8131H	Insured Vehicle No :	GBH7640R
Date of Loss:	30/01/2021	Nature of Claim:	TP
		Claim No:	1023094640SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBD8131H	Engine No:	KB602384
Make & Model:	SYM GTS 200, 172cc	Chassis No:	RFGLM18WX9S000940
Reg. Date:	07/08/2009 (Man. Year: 2009)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	172 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/90 R13	Rear Tyre Size:	130/70 R13
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,984.96	2,723.71	6,261.25	69.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	430.00	690.00	61.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,104.96	3,153.71	6,951.25	68.79
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	10,104.96	2,500.00	7,604.96	75.26
+ GST 7.00/7.00% (S\$)	707.35	175.00	532.35	75.26
Nett Amount (S\$)	10,812.31	2,675.00	8,137.31	75.26
+ Loss of Use (6.0 x S\$30.00/day) (S\$)		180.00		
Nett Liability (S\$)		2,855.00		
Global Sum Settlement (S\$)		2,850.00		

INSPECTION

Date of Assignment:	03/02/2021	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Date Inspected:	04/02/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*VISOR	Not Necessary	417.20 FL	*- FL
2	1		*SET MIRROR	Cut	394.00 FL	*70.00 FL
3	1		*HEADLAMP	Not Necessary	572.10 FL	*- FL
4	1		*FENDER	Not Necessary	234.20 FL	*- FL
5	1		*FRONT COWLING	Cut	317.10 FL	*317.10 FL
6	1		*FRONT COWLING GARNISH	Cut	146.20 FL	*146.20 FL
7	1		*FRONT COWLING EMBLEM	Necessary	47.30 FL	*47.30 FL
8	1		*FRONT RIM	Not Necessary	363.10 FL	*- FL
9	1		*FRONT RIM BEARING	Not Necessary	53.10 FL	*- FL
10	2		*FRONT SIGNAL RL	Not Necessary	292.40 FL	*- FL
11	1		*FRONT FORK ASSY	Bent	872.10 FL	*550.00 FL
12	1		*FRONT FORK STEM	Damaged	171.30 FL	*171.30 FL
13	2		*FRONT SIDE FAIRING RL	Cut	523.40 FL	*261.70 FL
14	2		*FLOOR BOARD RL	Not Necessary	774.40 FL	*- FL
15	2		*STEP BOARD RL	Deformed	552.60 FL	*276.30 FL
16	1		*FRAME COVER	Cracked	347.20 FL	*347.20 FL
17	1		*SIDE STAND	Not Necessary	136.20 FL	*- FL
18	1		*MAIN STAND	Not Necessary	174.10 FL	*- FL
19	2		*REAR FOOT REAR RL	Cut	232.60 FL	*116.30 FL
20	1		*TAIL COVER ASSY	Not Necessary	516.20 FL	*- FL
21	1		*TAIL COVER EMBLEM	Not Necessary	51.30 FL	*- FL
22	1		*PILLION BAR	Not Necessary	123.20 FL	*- FL
23	1		*AIR FILTER BOX	Not Necessary	374.20 FL	*- FL
24	1		*BELTING BOX	Not Necessary	427.10 FL	*- FL
25	2		*BRAKE LEVER RL	Not Necessary	231.20 FL	*- FL
26	1		*STEERING CONE	Necessary	138.50 FL	*138.50 FL
27	1		*HANDLE BAR	Not Necessary	232.30 FL	*- FL
28	2		*SET HANDLE BAR BALANCER	Not Necessary	102.60 FL	*- FL
29	1		*HANDLE BAR GRIP	Not Necessary	137.20 FL	*- FL
30	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
31	1		*STEERING CONE BEARING	Necessary	81.00 FS	*81.00 FS
32	1		*BOX BRACKET	Bent	165.00 FS	*165.00 FS
33	1		*REAR BOX	Cut	350.00 FS	*280.00 FS
34	1		*GRIP HOLDER	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,880.40	2,967.90
- List Item Discount on L Items 10.00/10.00% (\$)	895.44	244.19
Total Parts (\$)	8,984.96	2,723.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR AND REPLACE ACCIDENT AFFECTED AREA	New	500.00	200.00
2	CHECK WIRING	New	60.00	30.00
3	TRANSFER FRONT TYRE	New	40.00	0.00
4	FRAME ALIGNMENT	New	120.00	0.00
5	SPRAY PAINT	New	400.00	200.00
Gross Labour Cost (\$)			1,120.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >