

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0108/2021/GW
DATE : 02-Mar-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

4 days - ok - Jy - 30 Apr 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MDM NIENTIE NARWASTU ADMAJAYA
ADDRESS : 11 ARDMORE PARK
#08-04
SINGAPORE 259957
TELEPHONE : 978022125
TYPE OF CLAIM : OWN POLICY CLAIMS
POLICY NO :
VEHICLE NO : SJZ 620 E
MODEL CODE : AUDI A1 ADVANCED SB 1.0 TFSI
MODEL YEAR : 08/06/2020
ENGINE NO : DKJ043869
CHASSIS NO : WAUZZZGB3LR006221
MILEAGE :
DATE IN :
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30/01/2021
PLACE OF ACCIDENT : JUNCTION OF KIM SEND ROAD AND HAVELOCK ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 620 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	\$	1,100.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00		
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
SUB TOTAL LABOUR CHARGES		:	\$ 5,282.00	\$	2,652.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 620 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER	\$	1,634.00	\$ 1,307.20
2	FRONT BUMPER FIXING PARTS	\$	137.00	
3	FRONT BUMPER SPOILER-LH	\$	100.00	
4	FRONT BUMPER AIR GUIDE GRILLE-LH	\$	211.00	
5	FRONT BUMPER CLOSING ELEMENT	\$	167.00	
6	FRONT BUMPER GUIDE PROFILE-LH	\$	36.00	
7	FRONT BUMPER GUIDE SECTION-LH	\$	107.00	
8	FRONT FENDER-LH	\$	978.00	\$ 782.40
9	FRONT FENDER BRACE-LH	\$	54.00	
10	FRONT FENDER BRACKET-LH	\$	37.00	
11	FRONT FENDER BRACKET OUTER-LH	\$	37.00	
12	FRONT FENDER BRACKET INNER-LH	\$	14.00	
13	FRONT FENDER BRACET CENTRE-LH	\$	58.00	
14	FRONT WHEEL HOUSING LINER	\$	179.00	
15	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	\$	69.00	
16	FRONT FENDER BRACE-LH UPPER	\$	76.00	
17	LED HEADLIGHT-LH	\$	4,288.00	
18	LED HEADLIGHT LIFT CYLINDER-LH	\$	142.00	
19	FRONT ALUMINIUM RIM-LH	\$	962.00	
20	SUNDRIES	\$	300.00	
TOTAL SPARE PARTS		:	\$ 9,586.00	\$ 2,089.60
TOTAL LABOUR CHARGES		:	\$ 5,282.00	\$ 2,652.00
GRAND TOTAL		:	\$ 14,868.00	\$ 4,741.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LAOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT