

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 3/2/2021

To : MSIG INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : AIR CHINA LIMITED (SINGAPORE BRANCH)

AIG ASIA PACIFIC INSURANCE PTE LTD.

TPMSL6
Xiao Chen

Certificate Number : 2070133451

Accident Date : 15/01/2021

Vehicle Number : SMV1517A

MR2BE3BE700009243.

Make & Model : TOYOTA ALTIS
ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1	BOOT LID <i>Dischld</i>	\$ 956.40	✓
1	BOOT LID WEATHERSTRIP <i>ut</i>	\$ 270.60	✓
1	BOOT LID HINGE RH <i>Best</i>	\$ 167.40	✓
1	BOOT LID HINGE LH <i>Best</i>	\$ 167.40	✓
	BOOT LID LOCK <i>Dischld</i>	\$ 550.60	285
1	BOOT LID CHROME <i>new</i>	\$ 207.70	+ 295
1	BOOT LID REFLECTOR RH <i>cut</i>	\$ 729.20	✓
1	BOOT LID REFLECTOR LOWER CHROME <i>cut</i>	\$ 125.00	✓
1	BOOT LID EMBLEM "COROLLA" <i>new</i>	\$ 65.00	✓
1	BOOT LID EMBLEM "ALTIS" <i>new</i>	\$ 65.00	✓
1	BOOT LID INNER TRIMBOARD <i>new</i>	\$ 359.20	+ 295
1	BOOT LID LOGO <i>new</i>	\$ 95.60	✓
1	BOOTLID GLASS <i>new</i>	\$ 1,534.90	+ 295
1	BOOT LID REFLECTOR LH <i>cut</i>	\$ 729.20	✓
1	BOOT LID REFLECTOR CHROME LH <i>new</i>	\$ 125.00	✓
1	REAR BUMPER <i>Dischld</i>	\$ 560.10	58
1	REAR BUMPER RETAINER RH <i>new</i>	\$ 150.40	✓
1	REAR BUMPER RETAINER LH <i>new</i>	\$ 150.40	✓
1	REAR BUMPER TOWING COVER <i>Dischld</i>	\$ 25.00	345
1	REAR BUMPER REINFORCEMENT <i>Best</i>	\$ 780.60	✓
1	REAR END PANEL <i>Dischld</i>	\$ 616.20	165
1	REAR END PANEL TOP GARNISH <i>Dischld</i>	\$ 650.60	✓
1	RH REAR FENDER <i>Dischld</i>	\$ 1,085.90	✓
1	RH REAR FEDNER INNER SHIELD <i>new</i>	\$ 350.60	✓
1	LH REAR FENDER <i>Dischld</i>	\$ 1,085.90	✓
1	SPARE TYRE PANEL <i>Repair</i>	\$ 1,250.00	✓
1	RH TAILLAMP <i>Smashed</i>	\$ 1,560.70	385
1	RH TAILLAMP INNER PANEL <i>Dischld</i>	\$ 108.80	385
1	LH TAILLAMP <i>cut</i>	\$ 1,560.70	✓
1	RH TAILLAMP INNER GARNISH <i>cut</i>	\$ 45.00	20
	Sub Total	\$ 16,129.10	
	DISCOUNT 25% on Parts	\$ 4,032.28	
	Total	\$ 12,096.83	

Special Nett Item

10	REAR BUMPER CLIPS <i>new</i>	\$ 50.00	30
10	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	\$ 50.00	10

Boot Lid Hinge Best RH \$ 180.80

Boot Lid Hinge Best LH \$ 180.80

7623
5717.25

- 10 RH REAR FENDER INNER SHIELD CLIPS *new*
 1 RH REAR SPORT RIM *new*
 1 REAR BUMPER REVERSE SENSOR *Damaged*
 1 LH REAR SPROT RIM *new*

\$ 50.00
 \$ 450.00
 \$ 650.00
 \$ 1,200.00
 \$ 2,450.00

240
240

LABOUR CHARGE

- 1 TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS
 1 TO SPRAY PAINT ON ACCIDENT AREAS
 1 TO REMOVE AND REFIT REAR WINDSCREEN
 1 TO CONDUCT WIRNG AND REMOVE AND REFIT REVERSE
 1 TO REMOVE AND REFIT BOOT LID COMPARTMENT
 1 TO CHECKING WIRING AND TEST TAILLAMP
 1 TO RUST PROOFING ACCIDENT AREAS

\$ 2,500.00
 \$ 2,500.00
 \$ 150.00
 \$ 100.00
 \$ 150.00
 \$ 150.00
 \$ 150.00
 \$ 5,700.00
 \$ 20,246.83

1300
1200
120
50
60
30
100
2860

Sub Total
Grand Total

09 Days
8/8 L/S.
04/02/21

total: 8817.25
L/S: 7050. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: