



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

Vehicle No : <u>SJM T536M</u>	Accident Date : <u>2-2-2021</u>
Mileage :	Make / Model : <u>TOYOTA AITAR</u>
	CHASSIS : <u>MR053ZEE106128328</u>
Date :	Fax NO. : <u>6445 2934</u>

Items			
1	Front Bumper	car	465.10
2	Front Bumper side retainer	de	65.30
3	Front Bumper Beam	? bt ✓	358.70
4	Front Bumper clip	nd	38.00
5	Front Bumper Fog Lamp	? car ✓	201.40
6	Front Bumper Fog Lamp Cover	? dl ✓	161.41
7	Front Bumper lower lip	de	280.00
8	Front LH Fender	bt	415.30
9	Front LH Fender log (VXTI)	nd	41.90
10	Front LH Fender inner shield	de	127.30
11	Front LH Fender inner shield clip	nd	38.00
12	Front Headlamp LH	car	459.15
13	Front Bonnet	Ry	240.90
14	Front Bonnet Rubber	f x	110.35
15	Front Bonnet insulator	nd } x	219.40
16	Front Bonnet insulator clip	x	30.00
17	Front support panel	Ry	715.11
18	Front Bumper top Rubber	nd. x	75.15
19	Wiper tank & motor	de ✓	245.10 180
20			
			2828.56
		25%	2121.42



發福摩多車房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

SJM 7536 M

2-2-2021

Labour to straighten, repair, realign on affected area and replace damaged parts.	# 800 600
To spray painting on affected are. Bored, bumper, & fender	# 800. 600
To check on electrical wiring system & headlamp focus.	# 60.00 30
To conduct 4 wheel alignment	# 120. 1230
	2121.42
	1230
Est to repair 6 days	3351.42
	4/5 \$2700
Tanpin 97495749	# 4 days
4/2/21 @ 1530	
1/5 Resurvey after repair	
Tanpin @ khant.com	
4 days	6664.57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company