

YSK Auto Workshop

No. 1 Kaki Bukit Avenue 6, #01-49 (Autobay), Singapore 417883

H/P: 9640 2541

Email: dannyskyeo@gmail.com

TP Budget Direct.

Veron.

WBA7H32090EH38134

Vehicle number: SLG6168G

Vehicle Made & Model: BMW X2

Qty	List Items	Amount \$
1	Front fender - LH <i>Distorted</i>	891.50 ✓
1	Front fender emblem <i>neu</i>	81.50 ✓
1	Front fender wheel arch garnish <i>Dehd.</i>	331.25 ✓
1	Front fender inner shield <i>Dehd</i>	181.63 ✓
1	Front fender enclosure <i>Dehd</i>	120.42 ✓
1	Front bumper <i>neu</i>	1,481.30 X
1	Front door - LH <i>Distorted</i>	1,955.60 ✓
	Front door protector <i>Dehd</i>	341.20 ✓
1	Front door outer handle <i>neu</i>	190.60 X
1	Front door glass outer moulding <i>neu</i>	181.20 X
1	Front door glass run channel	226.45 X
1	Front door glass regulator <i>Dehd</i>	441.59 ✓
1	Front door glass regulator motor <i>neu</i>	431.60 X
1	Front door mechanism lock <i>Dehd</i>	581.90 ✓
1	Front door inner trim board <i>neu</i>	899.50 X
1	Front door insulation	151.60 X
1	Front door w/strip <i>neu</i>	231.20 ✓
1	Front door checker <i>neu</i>	130.50 X
1	Front door hinges @ 115 <i>neu</i>	230.00 X
1	Front door pillar <i>neu</i>	1,150.00 X
1	Front shock absorber - LH <i>Best neu</i>	680.90 ✓
1	Front shock absorber top mount <i>Dehd</i>	181.60 X
1	Front top arm <i>neu</i>	560.90 X
1	Front lower arm <i>Best</i>	580.60 ✓
1	Front knuckle arm <i>Dehd</i>	861.90 ✓
1	Front wheel hub <i>Dehd</i>	441.50 ✓
1	Front wheel bearing <i>Dehd</i>	231.60 ✓
1	Front anti roll bar <i>neu</i>	315.50 X
1	Front anti roll bar link <i>neu</i>	160.50 X
1	Side sill panel garnish <i>neu</i>	561.90 ✓
1	Rear door - LH <i>Distorted.</i>	1,831.60 ✓
1	Rear door outer handle <i>neu</i>	190.60 X

Vehicle number: SLG6168G

Vehicle Made & Model: BMW X2

Special Nett Items

1	Front sport wheel	at	1,500.00	1200.
1	Front tyre	new	800.00	x
1 set	F/R door black tape	New	300.00	100.
1 set	F/R door sound proofing	new	450.00	x
1	Rear sport wheel	at	1,500.00	1200.
1	Rear tyre	new	800.00	x
1 set	Side sill panel skirt set	crushed.	1,500.00	800
			<u>6,850.00</u>	

3300

Labour charges

To remove, refix front undercarriage	350.00	220.
To check wheel alignment	120.00	80.
To remove, refix front interior trims to assist repair	180.00	✓
To diagnose, erase fault memory after repair	450.00	150.
To respray undercoating	150.00	100
To respray painting and etc	1,800.00	1200.
Panel beating, cut, weld remove & replacing above parts	1,800.00	1000.
Total Labour	<u>4,850.00</u>	

2930

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

36,111.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 20069.28

A/S: 16K.

09 Days.