



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

3/2/2021

Accident date: 02/02/2021

Estimated repair cost for vehicle no: SJP6170A TOYOTA ALLION 1.5 A '09

CHASSIS: NZT2603033957

S/n	Qty	Items	U/price	Amount
1	1	Front Crossmember <i>Best</i>		1180.10 ✓
2	1	Front Anti Roll Bar		\$325.68 ✓
3	1	Front L/H Rim <i>lit</i>		\$650.00 400(SW) ✓
4	1	Front L/H Tyre <i>HE MR</i>		\$300.00 X
5	1	Front L/H Lower Arm <i>Best</i>		\$327.22 ✓
6	1	Front L/H Knuckle Arm <i>Deband</i>		\$321.55 ✓
7	1	Front L/H Knuckle Arm Bearing <i>MR</i>		\$191.40 ✓
8	1	Front L/H Shock Absorber <i>Best</i>		\$302.55 ✓
9	1	Front L/H Drive Shaft <i>Pangd</i>		\$1,012.60 ✓
10	1	Front Steering Rack <i>Best</i>		\$1,805.40 ✓
11	1	Front Engine Lower Cover <i>3 MP</i>		\$181.10 +
12	10	Front Engine Lower Cover Clips <i>1 MR</i>	\$6.50	\$65.00 +
13	1	Front Bonnet <i>Pegs</i>		\$974.45 X
14	2	Front Bonnet Hinge <i>HE MR</i>	\$132.25	\$264.50 +
15	1	Front L/H Head Lamp <i>covered</i>		\$672.85 ✓
16	1	Front Bumper <i>Deband</i>		\$498.00 ✓
17	1	Front L/H Bumper Side Retainer <i>MR</i>		\$121.35 45 ✓
18	10	Front Bumper Clips <i>MR</i>	\$6.50	\$65.00 30 ✓
19	1	Front L/H Bumper Fog Lamp Cover <i>3 MP</i>		\$132.25 +
20	1	Front Bumper Inner Sponge <i>HE MR</i>		\$191.40 +
21	1	Front Bumper Reinforcement		\$374.45 +
22	1	Front L/H Bumper Reinforcement Bracket <i>HE MR</i>		\$182.10 +
23	1	Front Bumper Lower Cover <i>HE MR</i>		\$227.45 +
24	1	Front L/H Fender <i>Distorted</i>		\$791.50 645 ✓
25	1	Front Fender Inner Panel <i>Pegs</i>		\$365.10 X
26	1	Front L/H Fender Cowling <i>Deband</i>		\$182.10 ✓
27	8	Front L/H Fender Cowling Clip <i>MR</i>	\$6.50	\$52.00 30 ✓
28	1	Front Support Panel <i>3 MP</i>		\$974.45 X
29	1	Front Grille <i>1 MR</i>		\$377.75 +

30	12	Front Grille Clip	NE new	\$6.50	\$78.00	+
31	1	Front L/H Door	Dented		\$866.95	✓
32	2	Front L/H Door Hinge	Best	\$85.00	\$170.00	✓
33		Front L/H Door Side Mirror Assy	Dented		\$685.95	✓
34	1	Front L/H Door Quarter Garnish	Missing		\$102.35	✓
35	1	Front L/H Door Outer Handle	3 Regis		\$156.80	+
36	1	Front L/H Door Outer Handle Cover			\$80.60	+
37	1	Front L/H Door Inner Lock	3 NP		\$561.60	+
38	1	Front L/H Door Inner Rubber	1 NP		\$261.10	+
39	1	Front L/H Door Inner Trim Board	cracked		\$781.80	633
40	1	Front L/H Door Inner Gear Motor Assy	Dented		\$625.65	325
41	2	Front L/H Door Frame Sticker	New	\$130.20	\$260.40	60(SN)
42	1	Rear L/H Door	Regis		\$972.70	+
43	2	Rear L/H Door Hinge	2	\$85.00	\$170.00	+
44	1	Rear L/H Door Inner Lock			\$561.60	+
45	1	Rear L/H Door Inner Rubber			\$261.10	+
46	1	Rear L/H Door Inner Trim Board	NP new		\$781.80	+
47	1	Rear L/H Door Inner Gear Motor Assy			\$625.65	+
48	2	Rear L/H Door Frame Sticker		\$130.20	\$260.40	+
49	1	Rear Bumper	Regis		\$1,218.85	+
50	1	Rear L/H Bumper Side Retainer	NP new		\$131.35	+
51	1	Rear L/H Fender	Regis		\$974.40	+
52	1	Rear L/H Fender Cowling	2		\$182.10	+
53	8	Rear L/H Fender Cowling Clip		\$6.50	\$52.00	+
54	1	Rear L/H Shock Absorber	NP		\$571.10	+
55	1	Rear L/H Axle	NP		\$2,821.10	+
56	1	Rear L/H Axle Bearing			\$672.10	+
57	1	Rear L/H Rim	NP new		\$650.00	X
58	1	Rear L/H Tyre	NP new		\$300.00	X
59	1	L/H Rocker Panel	NP new		\$1,250.00	X

10343.70

Subtotal :- \$28,119.75

7757.77

S.N: 460

Labour charges

To remove & refit steering rack, drive shaft, crossmember & top up oil

~~\$480.00~~ 120

To remove & refit L/H front & rear door glass, trim board, gear motor, outer & inner lock and rubber

~~\$550.00~~ 80

To remove & refit front undercarriage

~~\$350.00~~ 220

To remove & refit rear undercarriage

\$350.00 *

To check wheel alignment computer

\$150.00 80

To check wiring

\$100.00 30

Towing

\$150.00 60

Tuff kote

\$200.00 60

Panel Beating

\$3,000.00 800

Spray Painting

\$2,500.00 1400

Subtotal :- \$6,800.00

Total:- \$34,919.75

total: 11067.77

4/s: 88K

10 days

88K

10 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: